

---

## REF REPORT – HAZMAT ASSESSMENT BUILDING – MN03, MN05, MN09



Manning Base Hospital Redevelopment  
**26 York St**  
**Taree NSW 2430**

June 2023

*Survey conducted on March 2022*

**ENV Services Pty Ltd**

ABN 98 640 278 977

T: 1300 861 325

E: [admin@envsolutions.com.au](mailto:admin@envsolutions.com.au)

[www.envsolutions.com.au](http://www.envsolutions.com.au)

## Table of Contents

|            |   |          |
|------------|---|----------|
| 1          | INTRODUCTION.....   | 1        |
| 1.1        | Scope of Work .....   | 1        |
| 2          | SITE CHARACTERISTICS .....                                    | 3        |
| 3          | INSPECTION PROCEDURE.....                                     | 3        |
| 3.1        | Asbestos Containing Material (ACM) .....                      | 3        |
| 3.2        | Lead Paint Systems .....                                      | 4        |
| 3.2.1      | Lead Paint System Guidelines .....                            | 5        |
| 3.3        | Residual Lead in Dust.....                                    | 5        |
| 3.3.1      | Residual Lead in Dust Guidelines .....                        | 6        |
| <b>3.4</b> | <b>Synthetic Mineral Fibres (SMF) .....</b>                   | <b>6</b> |
| <b>3.5</b> | <b>Polychlorinated biphenyls (PCBs).....</b>                  | <b>7</b> |
| 3.6        | Photographic Record .....                                     | 7        |
| 3.7        | Inaccessible areas .....                                      | 7        |
| 4          | SURVEY SUMMARY .....  | 8        |
| 4.1        | Asbestos .....  | 8        |
| 4.1.1      | MN03 - Building 3 – Facility Maintenance Unit.....            | 8        |
| 4.1.2      | MN05 – Building 5 – Mortuary (Figure 2.0).....                | 8        |
| 4.1.3      | MN09 – Building 2 – Administration (Figure 3.0 and 3.1) ..... | 9        |
| 4.2        | Synthetic Mineral Fibres (SMF) .....                          | 11       |
| 4.3        | PolyChlorinated Biphenyls (PCBs).....                         | 11       |
| 4.4        | Lead Containing Paint.....                                    | 11       |
| 4.5        | Lead Containing Dust.....                                     | 11       |
| 5          | RECOMMENDATIONS .....   | 12       |
| 5.1        | Asbestos .....  | 12       |
| 5.2        | Synthetic Mineral Fibres (SMF) .....                          | 12       |
| 5.3        | Polychlorinated biphenyls (PCBs).....                         | 13       |
| 5.4        | Lead Paint Systems .....                                      | 13       |
| 5.5        | Residual Lead in Dust.....                                    | 13       |
| 6          | DEFINITIONS .....   | 15       |
| 7          | HAZMAT INFORMATION.....                                       | 18       |
| 7.1        | Concealed Asbestos.....                                       | 18       |
| 7.1.1      | Heater Banks .....  | 18       |
| 7.1.2      | Sprayed Fire Proofing Material .....                          | 18       |
| 7.1.3      | Pipe Lagging.....   | 18       |
| 7.1.4      | Underground Conduits & Pipes.....                             | 18       |
| 7.1.5      | Electrical Fuse Insulation.....                               | 19       |
| 7.2        | Assessment Factors for SMF.....                               | 19       |
| 7.2.1      | Bonded SMF .....  | 19       |
| 7.2.2      | Un-bonded SMF .....   | 19       |
| 7.3        | Risk Assessment Factors for Polychlorinated Biphenyls.....    | 20       |
| 7.3.1      | The handling and disposal of PCBs .....                       | 20       |
| 7.4        | Risk Assessment Factors for Lead Paint.....                   | 21       |
| 8          | REFERENCES.....   | 22       |

9 ATTACHMENTS .....23

10 DOCUMENT CONTROL.....E

List of Tables/Figures

Table 1: Site Characteristics..... 3

Table 2: Hazard Risk levels adopted from the US EPA Guidelines for Lead Surface Dust ..... 6

---

## 1 Introduction

---

This Review of Environmental Factors (REF) Report – Hazmat Assessment has been prepared by ENV Services Pty Ltd (ENV) at the request of Mace Group for Manning Base Hospital located at 26 York Street, Taree NSW 2430. The survey was undertaken to identify and confirm the existence of previously identified hazardous building materials (Hazmat) throughout specific buildings on-site, and to locate other previously unidentified Hazmat. The assessment was carried out by ENV's Licensed Asbestos Assessor Jake Rozyn (LAA001246) on Tuesday 8<sup>th</sup> to Tuesday 15<sup>th</sup> February 2022.

The contaminants of potential concern (COPC) included asbestos containing materials (ACM) and asbestos containing dust/ soil, paint systems and dust containing lead (Pb), synthetic mineral fibres (SMF) and Polychlorinated Biphenyls (PCB's) contained in capacitors in light fittings. Work was undertaken to assess the extent of hazardous materials within each building, establish any COPC and provide information to ensure that redevelopment works being undertaken are done so in a safe manner that minimises the risk of human exposure and environmental damage.

### 1.1 Scope of Work

The Project was announced in the NSW Government 2020 State Budget, under the Regional Health Infrastructure program, funded through the Restart NSW Fund. It is the second stage 2 of the expansion and refurbishment of Manning Base Hospital ('MBH') with a priority for improved patient accommodation. Identification of hazardous building materials prior to redevelopment works is required, and a scope of works developed for the safe removal of these.

These works are being delivered under Health Infrastructure with Mace as the appointed Project Managers for Stage 2.

Required works include an intrusive and minor destructive investigation of the following building proposed for demolition. This includes the following buildings:

- Building 2 – Nurse Quarters / Administration (MN09);
- Building 3 – Facilities Maintenance Unit (MN03); and
- Building 5 – Mortuary (MN05);

As a part of HI's due diligence prior to demolition of nominated hospital buildings, the Project Team have requested additional Hazmat investigations to provide clarity on existing items within the current Asbestos Register (2017) and secondary Hazmat Register (2015) in informing the detailed design and cost estimations. Any additional Hazmat items located during site investigations will be included in the updated register.

In light of these requirements, the scope of this assessment was to:

- Inspect all accessible areas of the nominated buildings to identify hazardous materials prior to redevelopment.
- Compile/ update a hazardous building materials register for the site; and
- Make recommendations for the on-going management/removal of the asbestos/hazardous materials.

The interior and exterior of the buildings were examined. Hazardous materials assessed included:

- Asbestos Containing Material (ACM) + contaminated dust and soil;
- Synthetic Mineral Fibre (SMF) materials;
- Polychlorinated Biphenyls (PCB's) contained in capacitors in light fittings; and,
- Lead (Pb) containing paint + contaminated dust.

---

## 2 Site Characteristics

---

**Table 1:** Site Characteristics

|   |   |
|---|---|
| <b>Lot &amp; DP:</b>                      | Lot 1 DP 101189   |
| <b>Site Address:</b>                      | 26 York Street, Taree NSW 2430  |
| <b>Type of Building/<br/>Age/ Levels:</b> | <p>MN03 - Steel structure with brick cladding build around 2002. There was no ACM sighted during the inspection, some SMF.</p> <p>MN05 - Single storey building built around 1950's constructed of solid brick and concrete. The original roof was an asbestos corrugated roof and has been removed and replaced, there was some debris found within the ceiling (no remediated) and the eaves have been identified as asbestos sheeting.</p> <p>MN09 - Three storey building built around 1950's constructed of solid brick and concrete There are a number of risers that run from the basement to the roof which contained asbestos but have since been remediated. There was asbestos contamination to the sub floor and ceiling spaces, however, these have been remediated (partially).</p> |

---

## 3 Inspection Procedure

---

The surveys were conducted to identify the presence and condition of COPC comprising of ACM + asbestos in dust + asbestos in soil, lead paint-based systems + lead in dust, SMF and PCBs. The procedure for identifying each COPC is summarised below.

### 3.1 Asbestos Containing Material (ACM)

This component of the assessment was carried out in accordance with *“How to manage and control asbestos in the workplace – Code of practice Safe Work NSW”* (August 2019). During the HAZMAT survey sampling program, twenty-three (23) potential ACM samples were obtained from targeted areas.

Samples were collected and placed in plastic snap lock bags prior to being sent to the NATA accredited, Australian Safer Environment & Technology Pty Ltd (ASET) (NATA accreditation no. 14484).

Specific locations required for sampling included building materials that had previously been identified as asbestos containing materials based on assumptions and any additional materials that had not been previously identified. The following standards and codes were followed as part of the ACM component of works:

- SafeWork NSW Code of Practice How to Manage and Control Asbestos in the Workplace (August 2019); and,
- Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres: 2nd Edition [NOHSC: 3003 (2005)].

### **3.2 Lead Paint Systems**

During the HAZMAT survey sampling program, six (6) potential lead paint samples were obtained from specific areas across the two buildings. Samples were collected and placed in plastic snap lock bags prior to being sent to the NATA accredited laboratory, Octief (NATA accreditation no. 15172). All work was undertaken in accordance with AS 4361.1 — *2017 Guide to hazardous paint management. Part 1: Lead and other hazardous metallic pigments in industrial applications*, and, AS 4361.2— *2017 Guide to hazardous paint management. Part 2: Lead paint in residential public and commercial buildings* guidelines and was undertaken by a suitably qualified ENV staff member.

Specific locations required for sampling included building paint systems that had previously been identified as lead containing based on assumptions and any additional paint systems that had not been previously identified. The following standards and codes were followed as part of the lead paint systems component of works:

- New South Wales Work Health and Safety Regulation 2017 AS 4361.1— *2017 Guide to hazardous paint management. Part 1: Lead and other metallic pigments in industrial applications*;

- AS 4361.1— 2017 *Guide to hazardous paint management. Part 1: Lead and other hazardous metallic pigments in industrial applications; and,*
- AS 4361.2— 2017 *Guide to hazardous paint management. Part 2: Lead paint in residential public and commercial buildings.*

### **3.2.1 Lead Paint System Guidelines**

As outlined in AS 4361.1— 2017 *Guide to hazardous paint management. Part 1: Lead and other hazardous metallic pigments in industrial applications*, lead based paint is defined as paint containing more than 0.1% weight for weight (w/w).

### **3.3 Residual Lead in Dust**

Seven (7) potential lead dust swab samples were obtained from ceiling cavities in Building 2 (MN09). All samples were submitted to a NATA accredited laboratory and analysed in accordance with Australian Standard AS 4361.2:2017 *Guide to Hazardous Paint Management – Part 2: Lead Paint in Residential, Public and Commercial Buildings*, and AS ISO/IEC 17025:2017 *General requirements for the competence of testing and calibration laboratories*.

Specific locations required for sampling included areas identified as being affected during the redevelopment works. No previous lead in dust sampling had occurred at the site. The following standards and codes were followed as part of the residual lead in dust component of works:

- *Safe Work Australia, Workplace Exposure Standards For Airborne Contaminants (18 April 2013);*
- AS 4361.1— 2017 *Guide to hazardous paint management. Part 1: Lead and other hazardous metallic pigments in industrial applications; and,*
- AS 4361.2— 2017 *Guide to hazardous paint management. Part 2: Lead paint in residential public and commercial buildings.*



### 3.3.1 Residual Lead in Dust Guidelines

Dust suspected of lead content were sampled and analysed in accordance with the Australian Standard (AS) 4361.2 Guide to Lead Paint Management; Part 2 Residential and Commercial Buildings.

The newly revised Australian and New Zealand Standard for managing lead containing materials in residential and commercial places (AS/NZS 4361.2-2017 Guide to lead paint management Part 2: Residential and Commercial Buildings) no longer provides guidance for lead surface dust levels. These levels are comparative to the NSW EPA document Managing Lead Contamination in Home Maintenance, Renovation and Demolition Practices: A Guide to Councils.

In the absence of Australian guidance for lead dust, ENV have adopted the assessment criteria from the US EPA literature. The US EPA assessment criteria for lead surface dust can be found in the table below:

**Table 2: Hazard Risk levels adopted from the US EPA Guidelines for Lead Surface Dust**

| Area                    | Commercial Facilities | Residential, Hospitals, Schools and Childcare Facilities |
|-------------------------|-----------------------|--|
| Exterior surface        | 8 mg/m <sup>2</sup>   | 4.3 mg/m <sup>2</sup>                                    |
| <b>Ceiling dust</b>     | 8 mg/m <sup>2</sup>   | <b>4.3 mg/m<sup>2</sup></b>                              |
| Interior surface        | 5 mg/m <sup>2</sup>   | 2.7 mg/m <sup>2</sup>                                    |
| Floors and eating areas | 1 mg/m <sup>2</sup>   | 0.43 mg/m <sup>2</sup>                                   |

### 3.4 Synthetic Mineral Fibres (SMF)

This component of the assessment was carried out in accordance with the guidelines documented in the *“Code of practice for the safe use of synthetic mineral fibres”* [NOHSC: 2006(1990)]. This report broadly identifies SMF materials found or suspected of being present during the survey based on a visual assessment.

### 3.5 Polychlorinated biphenyls (PCBs)

Detailed information on the ballasts in fluorescent tube light fittings and other electrical equipment are cross referenced to the document “*Identification of PCB containing capacitors information booklet: An information booklet for electricians and electrical contractors*”. (ANZECC 1997). No PCBs were identified.

### 3.6 Photographic Record

Photographs of the property as it existed on the day of the survey are provided at **Attachment 1**.

### 3.7 Inaccessible areas

The aim of the survey undertaken has been to locate, *as far as is reasonably practicable*, the presence of any hazardous substance(s) in the building and assess their condition.

This inspection has been undertaken in a **semi-destructive** manner and as such, there may be areas where ACM exists which have not been detected. This could include:

- Within wall cavities;
- beneath floors/slabs;
- within plant and equipment (such as AC ducts);
- hidden pipe work;
- ceiling spaces and voids; and
- other encapsulated areas.

Areas that were not assessed during the inspection due to buildings currently being occupied must be considered prior to demolition. An additional *destructive* inspection may be required for these areas, which allows access to areas otherwise hidden.

It is also not feasible to sample all materials suspected of containing asbestos. Where a sample has been positively identified by laboratory analysis as containing asbestos, other similar materials within the building may be referenced to that sample. In such cases, these similar materials are **presumed** or assumed to contain asbestos. Most presumed materials were sampled and NATA analysed.

---

## 4 Survey Summary

---

### 4.1 Asbestos

twenty-three (23) asbestos samples were taken from within, beneath and around the buildings. Samples were taken from previously assumed positive asbestos building materials, any large quantity building materials that may have previously been under sampled, large potentially contaminated areas and any unidentified ACMs. The samples included fibre cement sheeting, bituminous materials, putty, dust and debris, and lagging.

Practical Environmental Solutions (PES) completed Asbestos Audits of building MN09 in November 2017. Specific areas presumed during this inspection were targeted for testing in the current survey, with results included this report. This is summarised within targeted survey Hazmat register in Attachment 1.

The **key** findings include, but are not limited to (consult Hazmat Register for comprehensive list):

#### 4.1.1 MN03 - Building 3 – Facility Maintenance Unit

- No asbestos containing materials identified. 2 suspected ACM were tested and returned inconclusive.

#### 4.1.2 MN05 – Building 5 – Mortuary (Figure 2.0)

- Flat fibre cement asbestos sheeting identified to eave soffits and internal ceiling lining to storage room. A moulded fibre cement door jamb was also identified to western entry.
- Existing Hazardous Materials Register (2015) identified friable asbestos within the ceiling cavity remaining from previously removed corrugated asbestos roof. The survey confirmed the presence of a spray-applied encapsulant solution to all areas of the ceiling cavity; white in colour. Remediation is assumed to have been undertaken in July 2015. No clearance certification was provided to ENV. Again, ENV consider any porous and semi-porous encapsulated materials as non-friable asbestos contaminated materials and must be removed and disposed as such.

Extent of contaminated areas can be found in Figures in Attachment 3.

### 4.1.3 MN09 – Building 2 – Administration (Figure 3.0 and 3.1)

- Asbestos containing bituminous membrane identified on Level 01 balcony above conference room, and first floor balcony (not on small side awning beneath balcony ledge).
- Asbestos containing bituminous expansion joints on Level 02 east and west balconies. Existing register presumed asbestos containing bituminous membrane on these balconies, however, no evidence was found to confirm this.
- Existing Hazardous Materials Register (2015) identified extensive contamination of service risers and ceiling cavities from “asbestos cloth encased insulation to pipe work” and “Amosite Asbestos insulation debris to ceiling space”. Based on information provided to ENV from MACE, remediation of the following areas was undertaken in July 2015;
  - The roof void space above the three (3) story section of MN09 known as the ‘North Wing’;
  - The roof space above the two (2) story section of MN09 known as the ‘West Wing’;
  - The internal, utility service risers to both the ‘North Wing’ and ‘West Wing’ and;
  - The subfloor space beneath the ‘North Wing’ of MN09.

Husky Demolitions Pty Ltd was the engaged Class A (friable) - licensed asbestos removal contractor for the project with Hazmat Services (Hazmat) providing occupational hygiene services. PES was then engaged in March 2016 to provide:

- A thorough inspection of the locations from where the friable asbestos containing material (ACM) had since been removed;
- Analytical clearance, dust sampling of cleaned surfaces within the above spaces (not including the utility risers as these were previously sampled by Hazmat) and their immediate surrounds and;
- Preparation of an Asbestos Clearance Certificate for the affected spaces including photo identification.

The result of the clearance certificate are as follows:

*Visually, all identified asbestos-containing material had been removed from the affected areas. The removal areas and immediate surrounds had been cleaned to a practically achievable standard. We confirmed the presence of a spray-applied encapsulant solution to all areas of each removal area; white in colour.*

*Based on the visual clearance inspection, results of the para-occupational clearance atmospheric monitoring (done by Hazmat) and analytical clearance sampling by PES, we are confident that the areas identified above have been remediated of the hazard of concern, asbestos. The areas are safe for occupation and normal use.*

*PES is satisfied that these spaces had been cleaned to a practically achievable standard and were effectively remediated of the asbestos hazard.*

On assessment of this information and following recent surveys, although these areas (specifically the ceiling spaces, service risers, subfloor) have been “cleaned to a practically achievable standard”, the fact that porous and semi-porous materials are present (horse hair plaster, timber trusses and brick work) and a “spray-applied encapsulant solution” was used to all areas, ENV consider these porous and semi-porous encapsulated materials as non-friable asbestos contaminated materials and must be removed and disposed as such.

- Additionally, within the subfloor (north wing), contaminated surface soils have been encapsulated with approximately 100 mm layer of line-pumped concrete. As such, this concrete encapsulation is considered asbestos contaminated. The contaminated surface soil contains friable asbestos from lagging debris, however, the vertical extent of contamination is unknown.
- The un-remediated subfloor of the “west wing” was visually investigated and assumed asbestos debris was identified. Asbestos cloth encased pipe work is also known to exist within this area. Based on this information, history of the north wing subfloor and limited access at time of investigations, ENV deem this area contaminated with friable asbestos.

Extent of contaminated areas can be found in Figures in Attachment 3.

## **4.2 Synthetic Mineral Fibres (SMF)**

SMF containing material were found in building MN09 generally consisted of:

- Synthetic Mineral Fibre (SMF) – internal insulation of hot water systems.
- Synthetic Mineral Fibre (SMF) – internal foil backed insulation in ceiling cavities.
- Synthetic Mineral Fibre (SMF) – pipe lagging on hot water and service lines and AC duct work (ceiling cavities and subfloors)

## **4.3 PolyChlorinated Biphenyls (PCBs)**

All light fittings internally appear to be new, which were assessed as not likely to contain PCBs.

## **4.4 Lead Containing Paint**

Six (6) samples of paint were collected and submitted for lead analysis. All samples returned lead concentrations above 0.1% and, therefore, were confirmed as lead containing paint. Details of paint systems can be found within targeted survey Hazmat register in Attachment 1.

## **4.5 Lead Containing Dust**

Seven (7) samples of dust were collected and submitted for lead analysis. Seven (7) samples returned lead concentrations above nominated levels of 4.3mg/m<sup>2</sup>. All samples were taken from ceiling cavities through some of the buildings. Where friable asbestos was known to exist within ceiling cavities, lead in dust samples were not taken. Details of lead in dust locations can be found within the targeted survey Hazmat register in Attachment 1.

---

## 5 Recommendations

---

All management principles should reflect the contractors Hazmat procedural processes when safely and effectively dealing with Hazmat.

### 5.1 Asbestos

Based on the findings of this hazardous materials survey, the recommendations regarding ACM are:

- ACM that has been identified in this survey must be removed prior to the commencement of demolition works.
- When asbestos removal works are to be undertaken, the person that commissions the works must ensure that this is undertaken by an appropriately licensed asbestos removal contractor. The asbestos removal works must be conducted under controlled asbestos removal working conditions in accordance with SafeWork NSW, How to Safely Remove Asbestos, Code of Practice, August 2019.
- A licensed asbestos assessor who is independent of the asbestos contractor must be engaged to provide asbestos air monitoring, visual clearances and any other requirement as outlined in SafeWork NSW, How to Safely Remove Asbestos, Code of Practice, August 2019.
- Detailed removal requirements will be outlined in a scope of work document compiled by ENV.

### 5.2 Synthetic Mineral Fibres (SMF)

Un-bonded (friable) or bonded SMF that has severely deteriorated has the potential of becoming airborne. Health effects that may occur with exposure to certain SMF materials include; irritation of the skin, eyes and upper respiratory tract. As such removal is the preferred option if such materials were found in accessible areas or air conditioning systems.

The selection of the most appropriate control measure should be determined from risk assessments and detailed knowledge of the workplace and activities. The following general principles may be applied:

- If the SMF is un-bonded (friable) or deteriorated, in a poor/unstable condition and accessible with risk to health from exposure, immediate access restrictions should be applied, and removal is required as soon as practicable;
- If the SMF is un-bonded (friable) or deteriorated, in a poor/unstable condition but in inaccessible areas (i.e. Ceiling space), removal is preferred. However, if removal is not immediately practicable, short-term control measures (i.e. restrict access, or provide personal protective equipment to personnel required to access the area etc.) may be employed until removal can be facilitated;
- If the SMF is bonded and in a poor/unstable condition; minimising disturbance and removal or encapsulation may be appropriate controls; and
- Prior to any demolition, partial demolition, renovation or refurbishment, synthetic mineral fibre materials likely to be disturbed by those works should be removed in accordance with the NOHSC Code of Practice for the Safe Use of Synthetic Mineral Fibres [NOHSC:2006 (1990)].

Further assessment of risk through airborne fibre monitoring can assist with decisions on the most appropriate, and urgency of, control measures.

### **5.3 Polychlorinated biphenyls (PCBs)**

No PCBs were identified during the survey.

### **5.4 Lead Paint Systems**

Any paint-based lead reported to have exceeded the adopted guideline of 0.1% should be adequately managed in accordance with the AS 4361.1— *2017 Guide to hazardous paint management. Part 1: Lead and other hazardous metallic pigments in industrial applications* document, AS 4361.2— *2017 Guide to hazardous paint management. Part 2: Lead paint in residential public and commercial buildings* document.

### **5.5 Residual Lead in Dust**

Any residual lead in dust reported to have exceeded the adopted guidelines (Table 2) should be adequately managed in accordance with the AS 4361.1— *2017 Guide to hazardous paint*



management. Part 1: Lead and other hazardous metallic pigments in industrial applications as well as the AS 4361.2— 2017 Guide to hazardous paint management. Part 2: Lead paint in residential public and commercial buildings. Should air monitoring be required, work should be undertaken in accordance with AS3640-2009 Workplace atmospheres - Method for sampling and gravimetric determination of inhalable dust and assessed against Safe Work Australia Workplace Exposure Standards for Airborne Contaminants (2013).

## 6 Definitions

---

|  |  |
|--|--|
| <i>Airborne asbestos:</i>                          | Any fibres of asbestos small enough to be made airborne. For the purposes of monitoring airborne asbestos fibres, only respirable fibres are counted.  |
| <i>Asbestos:</i>                                   | The asbestiform varieties of mineral silicates belonging to the serpentine or amphibole groups of rock forming minerals, including actinolite asbestos, grunerite (or amosite) asbestos (brown), anthophyllite asbestos, chrysotile asbestos (white), crocidolite asbestos (blue) and tremolite asbestos or a mixture of any of these. |
| <i>Asbestos containing material:</i>               | Any material or thing that, as part of its design, contains asbestos.  |
| <i>Asbestos-contaminated dust or debris (ACD):</i> | Dust or debris that has settled within a workplace and is (or is assumed to be) contaminated with asbestos.  |
| <i>Asbestos-related work:</i>                      | Work involving asbestos (other than asbestos removal work to which Part 8.7 of the WHS Regulations applies) that is permitted under the exceptions set out in Regulation 419(3), (4) and (5).  |
| <i>Asbestos removalist:</i>                        | Work involving asbestos (other than asbestos removal work to which Part 8.7 of the WHS Regulations applies) that is permitted under the exceptions set out in Regulation 419(3), (4) and (5).  |
| <i>Asbestos removal work:</i>                      | <ul style="list-style-type: none"> <li>■ Work involving the removal of asbestos or ACM</li> <li>■ Class A asbestos removal work or Class B asbestos removal work as outlined in Part 8.10 of the WHS Regulations.</li> </ul>   |

|                                      |  |
|--------------------------------------|--|
| <i>Competent person:</i>             | In relation to carrying out clearance inspections under Regulation 473, means a person who has acquired through training or experience, the knowledge and skills of relevant asbestos removal industry practice and holds a certification in relation to the specified VET course for asbestos assessor work or a tertiary qualification in occupational health and safety, occupational hygiene, science, building, construction or environmental health. For all other purposes, competent person means a person who has acquired through training, qualification or experience, the knowledge and skills to carry out the task. |
| <i>Exposure standard:</i>            | For asbestos, is a respirable fibre level of 0.1 fibres/ml of air measured in a person's breathing zone and expressed as a time weighted average fibre concentration calculated over an eight-hour working day and measured over a minimum period of four hours in accordance with: <ul style="list-style-type: none"><li>■ the Membrane Filter Method;</li><li>■ a method determined by the relevant regulator.</li></ul>   |
| <i>Friable asbestos:</i>             | Means material that is in a powder form or that can be crumbled, pulverised or reduced to a powder by hand pressure when dry, and contains asbestos.   |
| <i>GHS:</i>                          | Globally Harmonised System of Classification and Labelling of Chemicals.   |
| <i>Licensed asbestos assessor:</i>   | A person who holds an asbestos assessor licence.   |
| <i>Licensed asbestos removalist:</i> | A person conducting a business or undertaking who is licensed under the WHS Regulations to carry out Class A or Class B asbestos removal work.   |

*Naturally occurring asbestos (NOA):* The natural geological occurrence of asbestos minerals found in association with geological deposits including rock, sediment or soil.

*Non-friable asbestos:* Material containing asbestos that is not friable asbestos, including material containing asbestos fibres reinforced with a bonding compound.

*Respirable asbestos:* An asbestos fibre that:

- is less than 3-micron metres ( $\mu\text{m}$ ) wide;
- more than 5-micron metres ( $\mu\text{m}$ ) long;
- has a length to width ratio of more than 3:1.

---

## 7 HAZMAT Information

---

### 7.1 Concealed Asbestos

#### 7.1.1 Heater Banks

Ducted air conditioning systems generally have heater banks contained within the duct-work near the air-handling plant. These are used to control the temperature of the cooled air. Where possible these are identified during an assessment, and, are tested for asbestos materials.

However, depending on the design of the air conditioning system, this duct-work may be installed within the ceiling or roof space and therefore may not be easily accessible.

#### 7.1.2 Sprayed Fire Proofing Material

To protect steel members in case of fire, it was commonplace to spray structural steel members with an asbestos material. This protected the steel member from heat damage.

This structural steel may be located within the building structure and not be readily accessible. Identifying the presence of sprayed asbestos material can be difficult.

No guarantee can be given that the assessment has identified all such material.

#### 7.1.3 Pipe Lagging

Depending on the nature of the building and its former use, there may be or may have been, steam and hot water pipes. Steam and hot water pipes within buildings are generally lagged with insulation material to conserve heat. In older buildings, this lagging may contain asbestos due to its insulating properties.

#### 7.1.4 Underground Conduits & Pipes

Manholes, pits and conduits hold communication and electrical cable. Older conduits and pits may contain fibre cement materials with fibres made up of either asbestos or cellulose.

The most likely scenario for disturbance of potential or actual ACM will be during maintenance and upgrade of the in-ground network infrastructure consisting of non-plastic pits and conduits.

Asbestos piping was also historically used in underground water and sewer services. These assets may be concealed and therefore difficult to detect during an Asbestos Assessment.

### **7.1.5 Electrical Fuse Insulation**

A past practice was to insulate the inside of commercial/industrial type fuses and meter boards with an asbestos material. This material is concealed within the electrical fuse holder.

It is recommended that when work is planned to be conducted on the electrical fuse panels, the electrical trades person shall provide the fuses to ENV for analysis of the material for asbestos content prior to any works being conducted.

## **7.2 Assessment Factors for SMF**

Risk assessment factors for Synthetic Mineral Fibre is very similar for asbestos products, where evidence of damage, accessibility, likelihood of disturbance etc is used when assessing SMF materials. Similarly, SMF condition, accessibility and risk status headings used above for asbestos can be applied to SMF materials. There are two basic forms of SMF insulation, bonded and un-bonded.

### **7.2.1 Bonded SMF**

Bonded SMF is where adhesives or cements have been applied to the SMF before delivery and the SMF product has a specific shape.

### **7.2.2 Un-bonded SMF**

Un-bonded SMF has no adhesives or cements and the SMF is loose material packed into a package.

Removal of bonded materials is easier and less hazardous than removal of un-bonded SMF material.

### **7.3 Risk Assessment Factors for Polychlorinated Biphenyls**

PCB containing ballasts were banned in 1976. Generally most fluorescent lights installed prior to 1976 have been now changed, apart from lights in store rooms and undercroft areas which are rarely used.

PCBs can enter the body in three ways:

- By swallowing contaminated food or drink.
- By absorption through the skin.
- By inhaling the vapour. However, vapour concentrations at room temperature are not significant.

Once the PCBs are in the body, they tend to lodge in the body fat and stay there for a considerable time. The very stability which makes them such useful materials prevents the body from eliminating them quickly.

Whatever the method of entry, excessive body contamination can cause long term health problems with the skin, eyes, hair and liver. PCBs are listed as a carcinogenic substance

#### **7.3.1 The handling and disposal of PCBs**

PCB containing equipment (capacitors, ballasts, etc.) is to be placed in a polyethylene bag which then is to be placed in a sealable metal container. This container must be clearly marked with the details of the contents and must be maintained in good order (that is, no visible signs of damage or corrosion). If some of these materials are leaking, the container should be partially filled with an absorbent material, such as a commercial absorbent, kitty litter or a diatomaceous earth. The plastic wrapped leaking components can then be placed in the container

The PPE should be worn when removing capacitors from light fittings in case Polychlorinated Biphenyls material leaks from the capacitor housing. Generally, metal-cased capacitors contain PCBs. Plastic-cased capacitors usually do not.

However, all leaking capacitors should be treated as if they contain PCBs unless proven otherwise. PCB containing ballasts should be segregated, transported and disposed of in accordance with the *Polychlorinated Biphenyl (PCB) Chemical Control Order 1997*.

## **7.4 Risk Assessment Factors for Lead Paint**

Lead paint, as defined by Australian Standard AS4361.2 – 1998 Guide to Lead Paint Management – Part 2: Residential and Commercial Property's, is that which contains more than 0.1% lead by weight.

Lead carbonate (white lead) was once the main white pigment in paints for houses and public property. Paint with lead pigment was manufactured up until the late 1960's, and in 1969 the National Health and Medical Research Council's Uniform Paint Standard was amended to restrict lead content in domestic paint. Lead in any form is toxic to humans when ingested or inhaled, with repeated transmission of particles cumulating in lead poisoning.

Lead paint is assessed based on two potential routes of exposure. Firstly, by the likelihood of inhalation or ingestion by people working near the paint and secondly, by the condition of the paint. Paint that is flaking or in poor condition is more likely to be ingested than paint that is in a good, stable condition.



---

## 8 References

---

- AS 4361.1— 2017 Guide to hazardous paint management. Part 1: Lead and other hazardous metallic pigments in industrial applications.
- AS 4361.2— 2017 Guide to hazardous paint management. Part 2: Lead paint in residential public and commercial buildings.
- Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres: 2nd Edition [NOHSC: 3003 (2005)].
- New South Wales Work Health and Safety Regulation 2017 AS 4361.1— 2017 Guide to hazardous paint management. Part 1: Lead and other metallic pigments in industrial applications.
- SafeWork NSW Code of Practice How to Manage and Control Asbestos in the Workplace (August 2019).
- Safe Work Australia, Workplace Exposure Standards For Airborne Contaminants (18 April 2013).
- Work Health and Safety Regulations 2011 (Chapter 8 – Asbestos) (As Amended 21 December 2012)
- National Occupational Health and Safety Commission, *Code of Practice for the management and control of asbestos in workplaces* (NOHSC:2018), April 2005.
- National Code of Practice for the safe use of Synthetic Mineral Fibres [NOHSC: 2006(1990)].

## 9 Attachments

---

|              |   |
|--------------|---|
| Attachment 1 | Targeted Survey Hazmat Register (includes PES 2017 Asbestos Register) |
| Attachment 2 | Photographs (PES – 2017 and ENV – 2022)                               |
| Attachment 3 | Figures   |
| Attachment 4 | Laboratory Results  |

---

**ATTACHMENT 1**

---

**Targeted Survey Hazmat Register (includes PES 2017 Asbestos Register)**

**BUILDING - Engineering / Workshops**

**NO ASBESTOS IDENTIFIED DURING THE INSPECTION**

| Survey Details                                      |                                  | Site Location                   |          |                       |                    | Site Description |   | Sample Details |                         |           |                |                |              | Risk Assessment Algorithm  |                 |                  |                |              |                             |             | Corrective Action |                    |                   |                           |                      |               |                    |  |
|---|----------------------------------|---------------------------------|----------|-----------------------|--------------------|------------------|---|----------------|-------------------------|-----------|----------------|----------------|--------------|----------------------------|-----------------|------------------|----------------|--------------|-----------------------------|-------------|-------------------|--------------------|-------------------|---------------------------|----------------------|---------------|--------------------|--|
| Survey Date   | Assessed by Company / Consultant | Workplace Name                  | Building | Floor                 | Room               | Location         | Application                               | Hazmat type    | Assumed Hazmat (Yes/No) | Sample ID | Sample results | Quantity (sqm) | ENV Photo id | A. Asbestos classification | B. Product Type | C. Accessibility | D. Labelled    | E. Condition | Hazmat Type (non mandatory) | Risk Rating | Control Measures  | Comments / Details | Reinspection Date | Consultant/Hygienist Name | Control Action Taken | Date actioned | Contractor details |  |
| <b>BUILDING MN03 - Engineering/ Workshops (FMU)</b> |                                  |                                 |          |                       |                    |                  |   |                |                         |           |                |                |              |                            |                 |                  |                |              |                             |             |                   |                    |                   |                           |                      |               |                    |  |
| 9/02/2022   | ENV                              | Manning Rural Referral Hospital | FMU      | Elevated level        | Male Toilet        | Wall             | Flat Fibre Cement Sheet                   | Asbestos       | No                      | AS09-8    | NAD            | NA             | 1            | NA                         | NA              | NA               | NA             | NA           | NA                          | NA          | NA                | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |  |
| 9/02/2022   | ENV                              | Manning Rural Referral Hospital | FMU      | Elevated level        | Male Toilet        | Toilet Divider   | Compressed Cement Sheet                   | Asbestos       | No                      | AS09-9    | NAD            | NA             | 2            | NA                         | NA              | NA               | NA             | NA           | NA                          | NA          | NA                | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |  |
| 9/02/2022   | ENV                              | Manning Rural Referral Hospital | FMU      | Elevated level        | Top work area      | Ceiling/ roof    | Foil backed SMF insulation to roof/ walls | SMF            | No                      | SMF09-1   | SMF detected   | TBA            | 3            | Non Friable 1              | Insulation 1    | Limited Access 1 | No Labelling 1 | Low Damage 1 | SMF                         | Very Low 5  | C15               | Remove             | NA                | Jake Rozyn                | NA                   | NA            | NA                 |  |
| 9/02/2022   | ENV                              | Manning Rural Referral Hospital | FMU      | Roof                  | -                  | Roof             | Corrugated fibreglass roof sheets         | SMF            | Yes                     | NA        | NA             | TBA            | 4            | Non Friable 1              | Insulation 1    | Limited Access 1 | No Labelling 1 | Low Damage 1 | SMF                         | Very Low 5  | C15               | Remove             | NA                | Jake Rozyn                | NA                   | NA            | NA                 |  |
| 9/02/2022   | ENV                              | Manning Rural Referral Hospital | FMU      | Ground floor          | MN0300006          | Cupboard         | Metal encased hot water system            | SMF            | Yes                     | -         | -              | TBA            | 5            | Non Friable 1              | Insulation 1    | Limited Access 1 | No Labelling 1 | Low Damage 1 | SMF                         | Very Low 5  | C15               | Remove             | NA                | Jake Rozyn                | NA                   | NA            | NA                 |  |
| 9/02/2022   | ENV                              | Manning Rural Referral Hospital | FMU      | External wall mounted | Outside lunch room | External wall    | Metal encased hot water system            | SMF            | Yes                     | -         | -              | TBA            | 6            | Non Friable 1              | Insulation 1    | Limited Access 1 | No Labelling 1 | Low Damage 1 | SMF                         | Very Low 5  | C15               | Remove             | NA                | Jake Rozyn                | NA                   | NA            | NA                 |  |

| Survey Details           |                                  | Site Location                   |          |              |                                | Site Description   |                         | Sample Details |                         |           |                                   |                  |              | Risk Assessment Algorithm  |                           |                   |                |                  |                                   |             | Corrective Action |                                 |                   |                            |                      |               |                    |
|--------------------------|----------------------------------|---------------------------------|----------|--------------|--------------------------------|--------------------|-------------------------|----------------|-------------------------|-----------|-----------------------------------|------------------|--------------|----------------------------|---------------------------|-------------------|----------------|------------------|-----------------------------------|-------------|-------------------|---------------------------------|-------------------|----------------------------|----------------------|---------------|--------------------|
| Survey Date              | Assessed by Company / Consultant | Workplace Name                  | Building | Floor        | Room                           | Location           | Application             | Hazmat type    | Assumed Hazmat (Yes/No) | Sample ID | Sample results                    | Quantity (sqm)   | PES Photo id | A. Asbestos classification | B. Product Type           | C. Accessibility  | D. Labelled    | E. Condition     | Asbestos Type (non mandatory)     | Risk Rating | Control Measures  | Comments / Details              | Reinspection Date | Consultant/ Hygienist Name | Control Action Taken | Date actioned | Contractor details |
| BUILDING MN05 - MORTUARY |                                  |                                 |          |              |                                |                    |                         |                |                         |           |                                   |                  |              |                            |                           |                   |                |                  |                                   |             |                   |                                 |                   |                            |                      |               |                    |
| 7/11/2017                | PES                              | Manning Rural Referral Hospital | Mortuary | External     | Door at south western entrance | Door jamb          | Moulded fibre cement    | Asbestos       | No                      | MT02      | Chrysotile & Amosite              | 1lin m           | 1            | Non Friable 1              | Flat Fibre Cement Sheet 1 | Full Access 3     | No Labelling 1 | Good condition 0 | Chrysotile & Amosite              | Very Low 6  | C2; C3; C4; C14;  | Remove.                         | 7/11/2022         | David McQueeney            | Noted in Register    | 7/11/2017     |                    |
| 7/11/2017                | PES                              | Manning Rural Referral Hospital | Mortuary | External     | Original building              | Eave soffit lining | Flat Fibre Cement Sheet | Asbestos       | No                      | Sample 1  | Chrysotile, Amosite & Crocidolite | 30m <sup>2</sup> | 2            | Non Friable 1              | Flat Fibre Cement Sheet 1 | Moderate Access 2 | Labelled 0     | Good condition 0 | Chrysotile, Amosite & Crocidolite | Very Low 4  | C1; C2; C3; C4;   | Good condition, manage in-situ. | 7/11/2022         | David McQueeney            | Noted in Register    | 7/11/2017     |                    |
| 7/11/2017                | PES                              | Manning Rural Referral Hospital | Mortuary | Ground Floor | Storage Room                   | Ceiling lining     | Flat Fibre Cement Sheet | Asbestos       | No                      | Sample 1  | Chrysotile, Amosite & Crocidolite | 10m <sup>2</sup> | 3            | Non Friable 1              | Flat Fibre Cement Sheet 1 | Moderate Access 2 | Labelled 0     | Good condition 0 | Chrysotile, Amosite & Crocidolite | Very Low 4  | C1; C2; C3; C4;   | Good condition, manage in-situ. | 7/11/2022         | David McQueeney            | Noted in Register    | 7/11/2017     |                    |

| ENV Inspection Sample Details |           |               |   |
|-------------------------------|-----------|---------------|---|
| Sampled (yes/no)              | Sample ID | Sample Result | Comment                                   |
| No                            |           |               | Previously sampled and confirmed positive |
| No                            |           |               | Previously sampled and confirmed positive |
| No                            |           |               | Previously sampled and confirmed positive |

| Survey Details           |                                  | Site Location                   |          |                         |                                   | Site Description                 |                                    | Sample Details |                         |           |   |                    |              | Risk Assessment Algorithm  |                 |                   |                |               |                             |             | Corrective Action |                    |                   |                            |                      |               |                    |    |
|--------------------------|----------------------------------|---------------------------------|----------|-------------------------|-----------------------------------|----------------------------------|------------------------------------|----------------|-------------------------|-----------|---|--------------------|--------------|----------------------------|-----------------|-------------------|----------------|---------------|-----------------------------|-------------|-------------------|--------------------|-------------------|----------------------------|----------------------|---------------|--------------------|----|
| Survey Date              | Assessed by Company / Consultant | Workplace Name                  | Building | Floor                   | Room                              | Location                         | Application                        | Hazmat type    | Assumed Hazmat (Yes/No) | Sample ID | Sample results                                | Quantity (sqm)     | ENV Photo id | A. Asbestos classification | B. Product Type | C. Accessibility  | D. Labelled    | E. Condition  | Hazmat Type (non mandatory) | Risk Rating | Control Measures  | Comments / Details | Reinspection Date | Consultant/ Hygienist Name | Control Action Taken | Date actioned | Contractor details |    |
| BUILDING MN05 - MORTUARY |                                  |                                 |          |                         |                                   |                                  |                                    |                |                         |           |   |                    |              |                            |                 |                   |                |               |                             |             |                   |                    |                   |                            |                      |               |                    |    |
| 10/02/2022               | ENV                              | Manning Rural Referral Hospital | Mortuary | Ceiling Cavity          | Original building                 | Timber trusses north             | Dust                               | Asbestos       | No                      | AS10-1    | NAD   | NA                 | 1            | NA                         | NA              | NA                | NA             | NA            | NA                          | NA          | NA                | NA                 | NA                | NA                         | Jake Rozyn           | NA            | NA                 | NA |
| 10/02/2022               | ENV                              | Manning Rural Referral Hospital | Mortuary | Ceiling Cavity          | Original building                 | Timber trusses middle            | Dust                               | Asbestos       | No                      | AS10-2    | NAD   | NA                 | 2            | NA                         | NA              | NA                | NA             | NA            | NA                          | NA          | NA                | NA                 | NA                | NA                         | Jake Rozyn           | NA            | NA                 | NA |
| 10/02/2022               | ENV                              | Manning Rural Referral Hospital | Mortuary | Ceiling Cavity          | Above ceiling slab to fridges 1-6 | Atop ceiling slab                | Waterproof membrane                | Asbestos       | No                      | AS10-3    | NAD   | NA                 | 3            | NA                         | NA              | NA                | NA             | NA            | NA                          | NA          | NA                | NA                 | NA                | NA                         | Jake Rozyn           | NA            | NA                 | NA |
| 10/02/2022               | ENV                              | Manning Rural Referral Hospital | Mortuary | Ceiling Cavity          | All                               | Porous and semi-porous materials | Encapsulated asbestos fibres       | Asbestos       | Yes                     | -         | Assume Amosite                                | TBA                | 4            | Non Friable 1              | Dust 2          | Moderate Access 2 | No Labelling 1 | Low Damage 1  | Assume Amosite              | Low 7       | C15               | Remove             | NA                | Jake Rozyn                 | NA                   | NA            | NA                 |    |
| 10/02/2022               | ENV                              | Manning Rural Referral Hospital | Mortuary | Ground Floor - External | Eastern side                      | Eastern side                     | Metal encased hot water system     | SMF            | Yes                     | -         | -   | TBA                | 5            | Non Friable 1              | Insulation 1    | Limited Access 1  | No Labelling 1 | Low Damage 1  | SMF                         | Very Low 5  | C15               | Remove             | NA                | Jake Rozyn                 | NA                   | NA            | NA                 |    |
| 10/02/2022               | ENV                              | Manning Rural Referral Hospital | Mortuary | Ground Floor - External | South side                        | External window frame            | Light brown/ white undercoat paint | Lead Paint     | No                      | Pb10-1    | 2.829% (>0.1%)                                | TBA                | 6            | Friable 2                  | Paint 1         | Limited Access 1  | No Labelling 1 | High Damage 3 | >0.1% Lead                  | Low 8       | C15               | Remove             | NA                | Jake Rozyn                 | NA                   | NA            | NA                 |    |
| 10/02/2022               | ENV                              | Manning Rural Referral Hospital | Mortuary | Ground Floor - External | All sides                         | External barge board             | Green paint                        | Lead Paint     | No                      | Pb10-2    | 2.522% (>0.1%)                                | TBA                | 7            | Friable 2                  | Paint 1         | Limited Access 1  | No Labelling 1 | High Damage 3 | >0.1% Lead                  | Low 8       | C15               | Remove             | NA                | Jake Rozyn                 | NA                   | NA            | NA                 |    |
| 10/02/2022               | ENV                              | Manning Rural Referral Hospital | Mortuary | Ground Floor - Internal | All rooms                         | Walls                            | White paint                        | Lead Paint     | No                      | Pb10-3    | 6.381% (>0.1%)                                | TBA                | 8            | Friable 2                  | Paint 1         | Limited Access 1  | No Labelling 1 | High Damage 3 | >0.1% Lead                  | Low 8       | C15               | Remove             | NA                | Jake Rozyn                 | NA                   | NA            | NA                 |    |
| 10/02/2022               | ENV                              | Manning Rural Referral Hospital | Mortuary | Ground Floor - Internal | All rooms                         | Door frames                      | Blue/ grey paint and undercoats    | Lead Paint     | No                      | Pb10-4    | 6.005% (>0.1%)                                | TBA                | 9            | Friable 2                  | Paint 1         | Limited Access 1  | No Labelling 1 | High Damage 3 | >0.1% Lead                  | Low 8       | C15               | Remove             | NA                | Jake Rozyn                 | NA                   | NA            | NA                 |    |
| 10/02/2022               | ENV                              | Manning Rural Referral Hospital | Mortuary | Ceiling cavity          | All rooms                         | Under roof sheets                | Foil backed SMF insulation to roof | SMF            | Yes                     | -         | -   | TBA                | 10           | Non Friable 1              | Insulation 1    | Limited Access 1  | No Labelling 1 | Low Damage 1  | SMF                         | Very Low 5  | C15               | Remove             | NA                | Jake Rozyn                 | NA                   | NA            | NA                 |    |
| 10/02/2022               | ENV                              | Manning Rural Referral Hospital | Mortuary | Ceiling cavity          | North                             | Ceiling cavity surfaces          | Dust                               | Lead in dust   | No                      | DS10-1    | 194mg/m <sup>2</sup> (>4.3mg/m <sup>2</sup> ) | All ceiling cavity | 11           | Friable 2                  | Dust 2          | Moderate Access 2 | No Labelling 1 | High Damage 3 | >4.3mg/m <sup>2</sup>       | Medium 10   | C15               | Remove             | NA                | Jake Rozyn                 | NA                   | NA            | NA                 |    |
| 10/02/2022               | ENV                              | Manning Rural Referral Hospital | Mortuary | Ceiling cavity          | Middle                            | Ceiling cavity surfaces          | Dust                               | Lead in dust   | No                      | DS10-2    | 13mg/m <sup>2</sup> (>4.3mg/m <sup>2</sup> )  | All ceiling cavity | 12           | Friable 2                  | Dust 2          | Moderate Access 2 | No Labelling 1 | High Damage 3 | >4.3mg/m <sup>2</sup>       | Medium 10   | C15               | Remove             | NA                | Jake Rozyn                 | NA                   | NA            | NA                 |    |
| 10/02/2022               | ENV                              | Manning Rural Referral Hospital | Mortuary | Ceiling cavity          | South side                        | Ceiling cavity surfaces          | Dust                               | Lead in dust   | No                      | DS10-3    | 3mg/m <sup>2</sup> (<4.3mg/m <sup>2</sup> )   | All ceiling cavity | 13           | NA                         | NA              | NA                | NA             | NA            | NA                          | NA          | NA                | NA                 | NA                | Jake Rozyn                 | NA                   | NA            | NA                 |    |

| Survey Details                           |                                  | Site Location                   |              |              |  | Site Description                         |                                | Sample Details |                           |               |                                   |                |              | Risk Assessment Algorithm  |                                  |                   |                |                  |                                   |             | Corrective Action   |  |                   |                           |                      | ENV Inspection Sample Details |                    |                  |                   |                        |  |  |
|--|----------------------------------|---------------------------------|--------------|--------------|--|--|--------------------------------|----------------|---------------------------|---------------|-----------------------------------|----------------|--------------|----------------------------|----------------------------------|-------------------|----------------|------------------|-----------------------------------|-------------|---------------------|--|-------------------|---------------------------|----------------------|-------------------------------|--------------------|------------------|-------------------|------------------------|--|--|
| Survey Date                              | Assessed by Company / Consultant | Workplace Name                  | Building     | Floor        | Room   | Location                                 | Application                    | Hazmat type    | Assumed Asbestos (Yes/No) | Sample ID     | Sample results                    | Quantity (sqm) | PES Photo id | A. Asbestos classification | B. Product Type                  | C. Accessibility  | D. Labelled    | E. Condition     | Asbestos Type (non mandatory)     | Risk Rating | Control Measures    | Comments / Details                           | Reinspection Date | Consultant/Hygienist Name | Control Action Taken | Date actioned                 | Contractor details | Sampled (yes/no) | Sample ID         | Sample Result          | Comment  |  |
| BUILDING - Building Two (Administration) |                                  |                                 |              |              |  |  |                                |                |                           |               |                                   |                |              |                            |                                  |                   |                |                  |                                   |             |                     |  |                   |                           |                      |                               |                    |                  |                   |                        |  |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | External     | 1st floor balcony  | Waterproofing membrane                   | Bituminous Product             | Asbestos       | No                        | Sample 12     | Chrysotile & Amosite              | 160m²          | 1            | Non Friable 1              | Bituminous Product 1             | Moderate Access 2 | Labelled 0     | Low Damage 1     | Chrysotile & Amosite              | Very Low 5  | C1; C2; C3; C4; C8; | Reasonably good condition, manage in-situ.   | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | Yes              | AS08-7            | Chrysotile             | Previously sampled and confirmed positive for Chrysotile and Amosite   |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | Ceiling Void | Above Room MN0901059 & 1058  | Waterproofing membrane                   | Bituminous Product             | Asbestos       | Yes                       | SP            | Strongly presumed                 | >50 m²         | 2            | Non Friable 1              | Bituminous Product 1             | Limited Access 1  | No Labelling 1 | Low Damage 1     | Presumed Asbestos                 | Very Low 5  | C1; C2; C3; C4;     | Good condition, manage in-situ.              | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | Yes              | AS09-5.1 & AS09-4 | NAD                    | Previously assumed positive. Sampling and analysis confirms NAD  |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | External     | 1st floor north east balcony Plus small side awning beneath balcony ledge. | Waterproofing membrane                   | Bituminous Product             | Asbestos       | No                        | AB08          | Chrysotile & Amosite              | 40m²           | 3            | Non Friable 1              | Bituminous Product 1             | Full Access 3     | Labelled 0     | Medium Damage 2  | Chrysotile & Amosite              | Low 7       | C1; C2; C3; C4;     | Good condition, manage in-situ.              | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | Yes              | AS08-3            | NAD                    | Previously sampled and returned positive for Chrysotile and Amosite, therefore, treat as positive. NB - "Plus small side awning beneath balcony ledge" has no waterproofing membrane         |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | External     | 2nd floor eastern balcony  | Floor                                    | Bituminous Product             | Asbestos       | No                        | SP            | Chrysotile & Amosite              | 50m²           | 4            | Non Friable 1              | Bituminous Product 1             | Moderate Access 2 | No Labelling 1 | Good condition 0 | Chrysotile & Amosite              | Very Low 5  | C1; C2; C3; C4;     | Good condition, manage in-situ.              | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | Yes              | AS08-12           | NAD                    | No bituminous membrane present, some black residues which were sampled and returned NAD. However, expansion joint mastic returned positive for Chrysotile (see ENV sampling below - AS08-13) |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | Ground Floor | Bulkhead outside MN0900059   | Infill panel                             | Flat Fibre Cement Sheet        | Asbestos       | No                        | AB05          | Chrysotile                        | 1.5m²          | 5            | Non Friable 1              | Flat Fibre Cement Sheet 1        | Moderate Access 2 | No Labelling 1 | Good condition 0 | Chrysotile                        | Very Low 5  | C1; C2; C3; C4;     | Good condition, manage in-situ.              | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | No               |                   |                        | Previously sampled and confirmed positive  |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | Ground Floor | Men's bathroom MN0900044   | Double ceiling lining plus manhole cover | Flat Fibre Cement Sheet        | Asbestos       | No                        | AB04          | Chrysotile                        | 6m²            | 6            | Non Friable 1              | Flat Fibre Cement Sheet 1        | Limited Access 1  | Labelled 0     | Low Damage 1     | Chrysotile                        | Very Low 4  | C1; C2; C3; C4;     | Deterioration of edges. Sealing recommended. | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | No               |                   |                        | Previously sampled and confirmed positive  |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | Ground Floor | Men's bathroom ceiling void MN0900044 and MN0900046                        | Fragments                                | Flat Fibre Cement Sheet        | Asbestos       | No                        | Refer to AB04 | Chrysotile                        | 1m²            | 7            | Non Friable 1              | Flat Fibre Cement Sheet 1        | Limited Access 1  | Labelled 0     | High Damage 3    | Chrysotile                        | Very Low 6  | C2; C4; C14; C15;   | Good condition, manage in-situ.              | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | Yes              | AS08-15           | Chrysotile             | Previously assumed, confirmed fragments and debris contain asbestos  |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | Ground Floor | Eave soffit outside room MN0900063   | Eave soffit lining                       | Flat Fibre Cement Sheet        | Asbestos       | No                        | PS            | Chrysotile                        | 5m²            | 8            | Non Friable 1              | Flat Fibre Cement Sheet 1        | Moderate Access 2 | Labelled 0     | Low Damage 1     | Chrysotile                        | Very Low 5  | C1; C2; C3; C4;     | Good condition, manage in-situ.              | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | No               |                   |                        | Previously sampled and confirmed positive  |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | Ground Floor | MN0900063  | Ceiling lining                           | Flat Fibre Cement Sheet        | Asbestos       | No                        | PS            | Chrysotile                        | 30m²           | 9            | Non Friable 1              | Flat Fibre Cement Sheet 1        | Moderate Access 2 | Labelled 0     | Good condition 0 | Chrysotile                        | Very Low 4  | C1; C2; C3; C4;     | Good condition, manage in-situ.              | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | No               |                   |                        | Previously sampled and confirmed positive  |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | Ground Floor | MN0900056  | Electrical switchboard x 2               | Flat Fibre Cement Sheet        | Asbestos       | Yes                       | SP            | Strongly presumed                 | 1m²            | 10           | Non Friable 1              | Flat Fibre Cement Sheet 1        | Limited Access 1  | No Labelling 1 | Good condition 0 | Presumed Asbestos                 | Very Low 4  | C1; C2; C3; C4;     | New label required                           | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | No               |                   |                        | Previously sampled and confirmed positive  |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | Ground Floor | MN0900056  | Infill panel                             | Flat Fibre Cement Sheet        | Asbestos       | No                        | SP            | Strongly presumed                 | 1m²            | 11           | Non Friable 1              | Flat Fibre Cement Sheet 1        | Limited Access 1  | Labelled 0     | Low Damage 1     | Presumed Asbestos                 | Very Low 4  | C1; C2; C3; C4;     | Good condition, manage in-situ.              | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | No               |                   |                        | Previously sampled and confirmed positive  |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | Ground Floor | North eastern entrance alcove  | Soffit lining                            | Flat Fibre Cement Sheet        | Asbestos       | Yes                       | AB            | Chrysotile & Amosite              | 6m²            | 12           | Non Friable 1              | Flat Fibre Cement Sheet 1        | Moderate Access 2 | Labelled 0     | Good condition 0 | Chrysotile & Amosite              | Very Low 4  | C1; C2; C3; C4;     | Good condition, manage in-situ.              | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | No               |                   |                        | Previously sampled and confirmed positive  |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | Ground Floor | Room MN0900028   | Electrical switchboard                   | Insulation Panel               | Asbestos       | Yes                       | SP            | Chrysotile, Amosite & Crocidolite | 1m²            | 13           | Non Friable 1              | Insulation Panel 1               | Limited Access 1  | No Labelling 1 | Good condition 0 | Chrysotile, Amosite & Crocidolite | Very Low 4  | C1; C2; C3; C4;     | Good condition, manage in-situ.              | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | No               |                   |                        | Previously sampled and confirmed positive  |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | Ground Floor | Subfloor of eastern wing   | Pipe                                     | Thermal Insulation to pipework | Asbestos       | No                        | PS            | Amosite                           | >50 LM         | 14           | Friable 2                  | Thermal Insulation to pipework 3 | No Access 0       | Labelled 0     | High Damage 3    | Amosite                           | Low 8       | C1; C2; C3; C4;     | Sealed off, previously sampled               | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | No               |                   |                        | Previously sampled and confirmed positive. Visual identification within subfloor not obtained.   |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | 1st Floor    | Upper cupboard to Room MN0901039   | Ceiling lining                           | Flat Fibre Cement Sheet        | Asbestos       | No                        | SP            | Chrysotile & Amosite              | 1m²            | 15           | Non Friable 1              | Flat Fibre Cement Sheet 1        | Limited Access 1  | No Labelling 1 | Good condition 0 | Chrysotile & Amosite              | Very Low 4  | C1; C2; C3; C4;     | Good condition, manage in-situ.              | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | Yes              | AS09-3.0          | Chrysotile and Amosite | Previously sampled and confirmed positive  |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | 1st Floor    | Upper cupboard to Room MN0901040 and 41                                    | Ceiling lining                           | Flat Fibre Cement Sheet        | Asbestos       | No                        | SP            | Chrysotile & Amosite              | 1m²            | 16           | Non Friable 1              | Flat Fibre Cement Sheet 1        | Limited Access 1  | No Labelling 1 | Good condition 0 | Chrysotile & Amosite              | Very Low 4  | C1; C2; C3; C4;     | Good condition, manage in-situ.              | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2017                    |                    | Yes              | AS09-3.0          | Chrysotile and Amosite | Previously sampled and confirmed positive  |  |
| 16/11/2017                               | PES                              | Manning Rural Referral Hospital | Building Two | 1st Floor    | Upper cupboard to Room MN0901042   | Ceiling lining                           | Flat Fibre Cement Sheet        | Asbestos       | No                        | SP            | Chrysotile & Amosite              | 1m²            | 17           | Non Friable 1              | Flat Fibre Cement Sheet 1        | Limited Access 1  | No Labelling 1 | Good condition 0 | Chrysotile & Amosite              | Very Low 4  | C1; C2; C3; C4;     | Good condition, manage in-situ.              | 16/11/2022        | David McQueeney           | Noted in Register    | 16/11/2022                    |                    | Yes              | AS09-3.1          | Chrysotile and Amosite | Previously sampled and confirmed positive  |  |

| Survey Details                                |                                  | Site Location                   |              |                |  | Site Description                 |                                    | Sample Details |                         |           |  |                    |              | Risk Assessment Algorithm  |                      |                   |                |               |  |             |                  | Corrective Action  |                   |                           |                      |               |                    |
|---|----------------------------------|---------------------------------|--------------|----------------|--|----------------------------------|------------------------------------|----------------|-------------------------|-----------|--|--------------------|--------------|----------------------------|----------------------|-------------------|----------------|---------------|--|-------------|------------------|--------------------|-------------------|---------------------------|----------------------|---------------|--------------------|
| Survey Date                                   | Assessed by Company / Consultant | Workplace Name                  | Building     | Floor          | Room   | Location                         | Application                        | Hazmat type    | Assumed Hazmat (Yes/No) | Sample ID | Sample results                               | Quantity (sqm)     | ENV Photo Id | A. Asbestos classification | B. Product Type      | C. Accessibility  | D. Labelled    | E. Condition  | Hazmat Type (non mandatory)              | Risk Rating | Control Measures | Comments / Details | Reinspection Date | Consultant/Hygienist Name | Control Action Taken | Date actioned | Contractor details |
| BUILDING MN09 - Administration (Building two) |                                  |                                 |              |                |  |                                  |                                    |                |                         |           |  |                    |              |                            |                      |                   |                |               |  |             |                  |                    |                   |                           |                      |               |                    |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 01       | NE Balcony   | Drain                            | Textile membrane                   | Asbestos       | No                      | AS08-1    | Chrysotile                                   | 1m <sup>2</sup>    | 1            | Non Friable 1              | Bituminous Product 1 | Moderate Access 2 | No Labelling 1 | Low Damage 1  | Chrysotile                               | Very Low 6  | C15              | Remove             | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 01       | NE Balcony   | Balcony                          | Textile membrane - To SMF membrane | Asbestos       | No                      | AS08-2    | NAD  | 40m <sup>2</sup>   | 2            | NA                         | NA                   | NA                | NA             | NA            | NA                                       | NA          | NA               | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 01       | NE Balcony   | Window                           | Window Putty                       | Asbestos       | No                      | AS08-4    | NAD  | -                  | 3            | NA                         | NA                   | NA                | NA             | NA            | NA                                       | NA          | NA               | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 00       | Under staircase west corner old build              | Under Carpet                     | VFT                                | Asbestos       | No                      | AS08-5    | NAD  | -                  | 4            | NA                         | NA                   | NA                | NA             | NA            | NA                                       | NA          | NA               | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 00       | Plant Rm25   | Hot water pipe                   | Gasket                             | Asbestos       | No                      | AS08-6    | NAD  | -                  | 5            | NA                         | NA                   | NA                | NA             | NA            | NA                                       | NA          | NA               | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 00       | MN0900053  | North wall infill panel          | Flat Fibre Cement Sheet            | Asbestos       | No                      | AS08-6.1  | NAD  | -                  | 6            | NA                         | NA                   | NA                | NA             | NA            | NA                                       | NA          | NA               | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 02       | Ceiling cavity                                     | North old build                  | Dust                               | Asbestos       | No                      | AS08-8    | NAD  | -                  | 7            | NA                         | NA                   | NA                | NA             | NA            | NA                                       | NA          | NA               | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 02       | Ceiling cavity                                     | Mid north old build              | Dust                               | Asbestos       | No                      | AS08-9    | NAD  | -                  | 8            | NA                         | NA                   | NA                | NA             | NA            | NA                                       | NA          | NA               | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 02       | Ceiling cavity                                     | West corner - hot water          | Gasket                             | Asbestos       | No                      | AS08-10   | NAD  | -                  | 9            | NA                         | NA                   | NA                | NA             | NA            | NA                                       | NA          | NA               | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 02       | Ceiling cavity                                     | West corner above toilets        | Dust                               | Asbestos       | No                      | AS08-11   | NAD  | -                  | 10           | NA                         | NA                   | NA                | NA             | NA            | NA                                       | NA          | NA               | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 02       | East balcony north wing                            | Expansion joint                  | Mastic                             | Asbestos       | No                      | AS08-13   | Chrysotile                                   | 10Lm               | 11           | Non Friable 1              | Bituminous Product 1 | Moderate Access 2 | No Labelling 1 | Low Damage 1  | Chrysotile                               | Very Low 6  | C15              | Remove             | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 02       | Internal east balcony exit                         | Under carpet                     | VFT                                | Asbestos       | No                      | AS08-14   | NAD  | -                  | 12           | NA                         | NA                   | NA                | NA             | NA            | NA                                       | NA          | NA               | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 9/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 02       | West balcony north wing                            | Expansion joint                  | Mastic                             | Asbestos       | No                      | AS09-2    | Chrysotile                                   | 10Lm               | 13           | Non Friable 1              | Bituminous Product 1 | Moderate Access 2 | No Labelling 1 | Low Damage 1  | Chrysotile                               | Very Low 6  | C15              | Remove             | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 9/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Subfloor       | Below toilets MN0900002                            | Flooring under bathroom tiles    | Compressed sheeting                | Asbestos       | No                      | AS09-5    | NAD  | -                  | 14           | NA                         | NA                   | NA                | NA             | NA            | NA                                       | NA          | NA               | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 9/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Subfloor       | Below toilets MN0900024                            | Flooring under bathroom tiles    | Compressed sheeting                | Asbestos       | No                      | AS09-6    | NAD  | -                  | 15           | NA                         | NA                   | NA                | NA             | NA            | NA                                       | NA          | NA               | NA                 | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 9/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Ceiling cavity | North wing and west wing                           | Porous and semi-porous materials | Encapsulated asbestos fibres       | Asbestos       | Yes                     | -         | Assume Amosite                               | TBA                | 16           | Non Friable 1              | Dust 2               | Moderate Access 2 | No Labelling 1 | Low Damage 1  | Assume Amosite                           | Low 7       | C15              | Remove             | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 9/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Subfloor       | Below southern building "west wing" near MN0900053 | External entry via small door    | Flat Fibre Cement Sheet Debris     | Asbestos       | Yes                     | -         | Assume Chrysotile, Amosite & Crocidolite     | All subfloor       | 17           | Friable 2                  | Debris 2             | Limited Access 1  | Labelled 0     | High Damage 3 | Assume Chrysotile, Amosite & Crocidolite | Low 8       | C15              | Remove             | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 02       | Ceiling cavity                                     | North old build                  | Lead in Dust                       | Lead           | No                      | DS08-1    | 45mg/m <sup>2</sup> (>4.3mg/m <sup>2</sup> ) | All ceiling cavity | 18           | Friable 2                  | Dust 2               | Moderate Access 2 | No Labelling 1 | High Damage 3 | >4.3mg/m <sup>2</sup>                    | Medium 10   | C15              | Remove             | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 02       | Ceiling cavity                                     | Mid north old build              | Lead in Dust                       | Lead           | No                      | DS08-2    | 14mg/m <sup>2</sup> (>4.3mg/m <sup>2</sup> ) | All ceiling cavity | 19           | Friable 2                  | Dust 2               | Moderate Access 2 | No Labelling 1 | High Damage 3 | >4.3mg/m <sup>2</sup>                    | Medium 10   | C15              | Remove             | NA                | Jake Rozyn                | NA                   | NA            | NA                 |
| 8/02/2022                                     | ENV                              | Manning Rural Referral Hospital | Building Two | Level 02       | Ceiling cavity                                     | West corner old build            | Lead in Dust                       | Lead           | No                      | DS08-3    | 9mg/m <sup>2</sup> (>4.3mg/m <sup>2</sup> )  | All ceiling cavity | 20           | Friable 2                  | Dust 2               | Moderate Access 2 | No Labelling 1 | High Damage 3 | >4.3mg/m <sup>2</sup>                    | Medium 10   | C15              | Remove             | NA                | Jake Rozyn                | NA                   | NA            | NA                 |

|           |     |                                 |              |              |                      |   |               |      |     |        |  |                    |    |               |              |                   |                |               |                       |            |     |        |    |            |    |    |    |
|-----------|-----|---------------------------------|--------------|--------------|----------------------|---|---------------|------|-----|--------|--|--------------------|----|---------------|--------------|-------------------|----------------|---------------|-----------------------|------------|-----|--------|----|------------|----|----|----|
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Level 02     | Ceiling cavity       | South old build   | Lead in Dust  | Lead | No  | DS08-4 | 17mg/m <sup>2</sup> (>4.3mg/m <sup>2</sup> ) | All ceiling cavity | 21 | Friable 2     | Dust 2       | Moderate Access 2 | No Labelling 1 | High Damage 3 | >4.3mg/m <sup>2</sup> | Medium 10  | C15 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Level 01     | NE Balcony old build | White paint on window frames                            | Lead in Paint | Lead | No  | Pb08-1 | 0.253% (>0.1%)                               | TBA                | 22 | Friable 2     | Paint 1      | Limited Access 1  | No Labelling 1 | High Damage 3 | >0.1% Lead            | Low 8      | C15 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Ground Floor | Outside MN0900058    | Paint on cement render walls                            | Lead in Paint | Lead | No  | Pb08-2 | 2.094% (>0.1%)                               | TBA                | 23 | Friable 2     | Paint 1      | Limited Access 1  | No Labelling 1 | High Damage 3 | >0.1% Lead            | Low 8      | C15 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Ground Floor | Outside MN0900057    | Paint on door frame                                     | Lead in Paint | Lead | No  | Pb08-3 | 1.361% (>0.1%)                               | TBA                | 24 | Friable 2     | Paint 1      | Limited Access 1  | No Labelling 1 | High Damage 3 | >0.1% Lead            | Low 8      | C15 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Level 02     | All                  | White paint on window frames                            | Lead in Paint | Lead | No  | Pb08-4 | 2.048% (>0.1%)                               | TBA                | 25 | Friable 2     | Paint 1      | Limited Access 1  | No Labelling 1 | High Damage 3 | >0.1% Lead            | Low 8      | C15 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Level 01     | MN0901046            | Blue paint to timer work                                | Lead in Paint | Lead | No  | Pb09-1 | 7.895% (>0.1%)                               | TBA                | 26 | Friable 2     | Paint 1      | Limited Access 1  | No Labelling 1 | High Damage 3 | >0.1% Lead            | Low 8      | C15 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Level 02     | All                  | Light green paint to walls                              | Lead in Paint | Lead | No  | Pb09-2 | 0.196% (>0.1%)                               | TBA                | 27 | Friable 2     | Paint 1      | Limited Access 1  | No Labelling 1 | High Damage 3 | >0.1% Lead            | Low 8      | C15 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Level 01     | Ceiling cavity       | West new build  | Lead in Dust  | Lead | No  | DS09-1 | 33mg/m <sup>2</sup> (>4.3mg/m <sup>2</sup> ) | All ceiling cavity | 28 | Friable 2     | Dust 2       | Moderate Access 2 | No Labelling 1 | High Damage 3 | >4.3mg/m <sup>2</sup> | Medium 10  | C15 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Level 01     | Ceiling cavity       | Middle new build  | Lead in Dust  | Lead | No  | DS09-2 | 5mg/m <sup>2</sup> (>4.3mg/m <sup>2</sup> )  | All ceiling cavity | 29 | Friable 2     | Dust 2       | Moderate Access 2 | No Labelling 1 | High Damage 3 | >4.3mg/m <sup>2</sup> | Medium 10  | C15 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Level 01     | Ceiling cavity       | East new build  | Lead in Dust  | Lead | No  | DS09-3 | 16mg/m <sup>2</sup> (>4.3mg/m <sup>2</sup> ) | All ceiling cavity | 30 | Friable 2     | Dust 2       | Moderate Access 2 | No Labelling 1 | High Damage 3 | >4.3mg/m <sup>2</sup> | Medium 10  | C15 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Basement     | Plant Rm 22          | Insulated pipe work                                     | Insulation    | SMF  | Yes | -      | -  | TBA                | 31 | Non Friable 1 | Insulation 1 | Limited Access 1  | No Labelling 1 | Low Damage 1  | SMF                   | Very Low 5 | C15 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Ground floor | MN0900053            | Foil backed insulation to roof                          | Insulation    | SMF  | Yes | -      | -  | TBA                | 32 | Non Friable 1 | Insulation 1 | Limited Access 1  | No Labelling 1 | Low Damage 1  | SMF                   | Very Low 5 | C16 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Level 01     | Ceiling cavity       | Foil backed insulation to roof new build                | Insulation    | SMF  | Yes | -      | -  | TBA                | 33 | Non Friable 1 | Insulation 1 | Limited Access 1  | No Labelling 1 | Low Damage 1  | SMF                   | Very Low 5 | C16 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Level 01     | Ceiling cavity       | Foil backed insulation to AC duct work new build        | Insulation    | SMF  | Yes | -      | -  | TBA                | 34 | Non Friable 1 | Insulation 1 | Limited Access 1  | No Labelling 1 | Low Damage 1  | SMF                   | Very Low 5 | C16 | Remove | NA | Jake Rozyn | NA | NA | NA |
| 8/02/2022 | ENV | Manning Rural Referral Hospital | Building Two | Level 02     | Ceiling cavity       | Foil backed insulation to water storage tanks old build | Insulation    | SMF  | Yes | -      | -  | TBA                | 35 | Non Friable 1 | Insulation 1 | Limited Access 1  | No Labelling 1 | Low Damage 1  | SMF                   | Very Low 5 | C16 | Remove | NA | Jake Rozyn | NA | NA | NA |



---


**ATTACHMENT 2**

---

**Photographs (PES – 2017 and ENV – 2022)**


## PHOTOGRAPHS

Photo 1:




AS09 – 8: No asbestos detected

Photo 2:



AS09 – 9: No asbestos detected

Photo 3:




SMF09 – 1: Synthetic mineral fibre detected

Photo 4:



SMF: Corrugated roof sheeting

Photo 5:



SMF: Hot water system insulation

Photo 6:



SMF: Hot water system insulation


**PHOTOGRAPHS**

**Photo 1:**



AS10 – 1: No asbestos detected

**Photo 2:**




AS10 – 2: No asbestos detected

**Photo 3:**



AS10 – 3: No asbestos detected

**Photo 4:**



Assume Amosite asbestos (non-friable)

Photo 5:



SMF: Hot water system insulation

Photo 6:




PB10 - 1: >0.1%

Photo 7:




PB10 - 2: >0.1%

Photo 8:



PB10 - 3: >0.1%

Photo 9:



PB10 – 4:  $>0.1\%$

Photo 10:



SMF: Foil backed insulation

Photo 11:



DS10 – 1:  $>4.3\text{mg}/\text{m}^2$

Photo 12:

No photo

DS10 – 2:  $>4.3\text{mg}/\text{m}^2$

**Photo 13:**

**No photo**

DS10 – 3: >4.3mg/m<sup>2</sup>

## PHOTOGRAPHS

Photo 1:



AS08 – 1: Chrysotile asbestos detected

Photo 2:




AS08 – 2: No asbestos detected

Photo 3:



AS08 – 4: No asbestos detected

Photo 4:



AS08 – 5: No asbestos detected



Photo 5:



AS08 – 6: No asbestos detected

Photo 6:



AS08 – 6.1: No asbestos detected

Photo 7:




AS08 – 8: No asbestos detected

Photo 8:



AS08 – 9: No asbestos detected

Photo 9:



AS08 – 10: No asbestos detected

Photo 10:



AS08 – 11: No asbestos detected

Photo 11:



AS08 – 13: **Chrysotile asbestos detected**

Photo 12:



AS08 – 14: No asbestos detected

Photo 13:



AS09 – 2: Chrysotile asbestos detected

Photo 14:



AS09 – 5: No asbestos detected

Photo 15:



AS09 – 6: No asbestos detected

Photo 16:



Example of subfloor surfaces following remediation in 2015. Porous and semi-porous surfaces encapsulated with white spray paint. Assumed non-friable contaminated material

Photo 17:




Assumed chrysotile, amosite and crocidolite debris

Photo 18:



DS08 – 1:  $>4.3\text{mg}/\text{m}^2$

Photo 19:



DS08 – 2:  $>4.3\text{mg}/\text{m}^2$

Photo 20:



DS08 – 3:  $>4.3\text{mg}/\text{m}^2$


## PHOTOGRAPHS

Photo 21:



DS08 – 4:  $>4.3\text{mg/m}^2$

Photo 22:



PB08 – 1:  $>0.1\%$

Photo 23:



PB08 – 2:  $>0.1\%$

Photo 24:




PB08 – 3:  $>0.1\%$

Photo 25:



PB08 - 4: >0.1%

Photo 26:



PB09 - 1: >0.1%

Photo 27:



PB09 - 2: >0.1%

Photo 28:



DS09 - 1: >4.3mg/m<sup>2</sup>

Photo 29:



DS09 – 2:  $>4.3\text{mg}/\text{m}^2$

Photo 30:



DS09 – 3:  $>4.3\text{mg}/\text{m}^2$

Photo 31:



SMF encased on pipework

Photo 32:

No Photo

SMF – Foil backed insulation to roof above MN0900053

**Photo 33:**




**SMF** – Foiled back insulation Level 01 “west wing”

**Photo 34:**

**No Photo**

**SMF** - Foil backed insulation to AC duct work Level 01 “west wing”

**Photo 35:**



**SMF** - Foil backed insulation to water storage tanks Level 02 “north wing”



---


**ATTACHMENT 3**

---

**Figures**



**LEGEND**

 Investigation Boundaries




**Figure 1 – Site Location**  
Manning Hospital Taree NSW

**Licensed Assessor:** Jake Rozyn  
**LAA License No:** LAA001246  
**Phone:** 0435 857 751

**Project:** HAZMAT Assessment  
**Client:** Health Infrastructure  
**Date:** 8-15 Feb 2022



**LEGEND**

 Non-friable contaminated ceiling cavity






**Figure 2.0 – ACM Ceiling Cavities MN05**  
Manning Hospital Taree NSW

**Licensed Assessor:** Jake Rozyn  
**LAA License No:** LAA001246  
**Phone:** 0435 857 751

**Project:** HAZMAT Assessment  
**Client:** Health Infrastructure  
**Date:** 8-15 Feb 2022



**LEGEND**


-  Bituminous membrane level 1
-  Bituminous expansion joints level 02 balconies
-  Non-friable contaminated ceiling cavities



**Figure 3 – Site Location**  
Manning Hospital Taree NSW

**Licensed Assessor:** Jake Rozyn  
**LAA License No:** LAA001246  
**Phone:** 0435 857 751

**Project:** HAZMAT Assessment  
**Client:** Health Infrastructure  
**Date:** 8-15 Feb 2022



**LEGEND**



Friable non-remediated subfloor



Non-friable remediated subfloor surfaces/  
friable soil under encapsulation slab



**Figure 3.1 – ACM Subfloor MN09**  
Manning Hospital Taree NSW

---

**ATTACHMENT 4**

---

**Laboratory Results**



**AUSTRALIAN SAFER ENVIRONMENT & TECHNOLOGY PTY LTD**

Suite 710/ 90 George Street Hornsby NSW 2077 PO Box 1644 Hornsby Westfield NSW 1635

Ph: 02 9987 2183 Fax: 02 9987 2151 Email: [aset@bigpond.net.au](mailto:aset@bigpond.net.au)

| ASET JOB NO: <u>AS6799144/102324/1-3</u>                                |           |       |      |           | Contact Name: Jake Rozyn   |   | Asbestos in Material | Asbestos in Soil | Asbestos in Dust | Asbestos Fibre Count | Asbestos in Water | Asbestos WA/NEPM | SMF |
|---|-----------|-------|------|-----------|--|---|----------------------|------------------|------------------|----------------------|-------------------|------------------|-----|
| Company Name & Address: ENV Solutions<br>PO Box 248<br>Ballina NSW 2478 |           |       |      |           | Job No: 216435   |   |                      |                  |                  |                      |                   |                  |     |
| Contact Ph: 0435 857 751  |           |       |      |           | Project Name: Taree Manning Hospital – B3  |   |                      |                  |                  |                      |                   |                  |     |
|   |           |       |      |           | Email Results to: <a href="mailto:jake@envsolutions.com.au">jake@envsolutions.com.au</a> ;<br><a href="mailto:labresults@envsolutions.com.au">labresults@envsolutions.com.au</a> |   |                      |                  |                  |                      |                   |                  |     |
|   | Sample ID | Date  | Type | Container | Sample Location  |   |                      |                  |                  |                      |                   |                  |     |
| 1   | SMF09-1   | 09/02 | Bulk | Bag       | FMU for ceiling insulation   |   |                      |                  |                  |                      |                   |                  | X   |
| 2   | AS09-8    | 09/02 | Bulk | Bag       | FMU male toilet wall   | X |                      |                  |                  |                      |                   |                  |     |
| 3   | AS09-9    | 09/02 | Bulk | Bag       | FMU male toilet dividers   | X |                      |                  |                  |                      |                   |                  |     |
| 4   |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 5   |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 6   |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 7   |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 8   |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 9   |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 10  |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 11  |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 12  |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 13  |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 14  |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 15  |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 16  |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 17  |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 18  |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 19  |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| 20  |           |       |      |           |  |   |                      |                  |                  |                      |                   |                  |     |
| Relinquished By: J.Rozyn  |           |       |      |           | Received By: <u>Kithin</u>   |   | Turn around time     |                  |                  | Method of Shipment   |                   |                  |     |
| Date & Time:  |           |       |      |           | Date & Time: <u>17/2/22 9am</u>  |   | 24 Hrs               | X                | 3 Days           |                      |                   |                  |     |
| Signature:  |           |       |      |           | Signature:   |   | 48 Hrs               |                  | 5 Days           |                      |                   |                  |     |

**URGEN**

**RECEIVED**  
17 FEB 2022  
BY: Kithin

Our ref : ASET99144 / 102324 / 1 - 3  
Your ref : 216435 - Taree Manning Hospital - B3  
**NATA Accreditation No: 14484**

17 February 2022

ENV Solutions  
PO Box 248  
Ballina NSW 2478

**Attn: Mr Jake Rozyn**

Dear Jake

### **Asbestos Identification**

This report presents the results of three samples, forwarded by ENV Solutions on 17 February 2022, for analysis for asbestos.

**1.Introduction:**Three samples forwarded were examined and analysed for the presence of asbestos.

**2. Methods :** The samples were examined under a Stereo Microscope and selected fibres were analysed by Polarized Light Microscopy in conjunction with Dispersion Staining method (**Australian Standard AS4964 - 2004 and Safer Environment Method 1 as the supplementary work instruction**) (**Qualitative Analysis only**).

**3. Results :** **Sample No. 1. ASET99144 / 102324 / 1. SMF09-1 - FMU for ceiling insulation.**  
Approx dimensions 4.0 cm x 3.0 cm x 0.3 cm  
The sample consisted of a fibrous mass of synthetic mineral fibres.  
**No asbestos detected.**

**Sample No. 2. ASET99144 / 102324 / 2. AS09-8 - FMU male toilet wall.**  
Approx dimensions 1.0 cm x 0.7 cm x 0.2 cm  
The sample consisted of fragments of a fibro plaster cement material containing organic fibres.  
**No asbestos detected. (Submitted sample is too small and a larger sample may produce a different result).**

**Sample No. 3. ASET99144 / 102324 / 3. AS09-9 - FMU male toilet dividers.**  
Approx dimensions 0.5 cm x 0.5 cm x 0.2 cm  
The sample consisted of fragments of a fibro plaster cement material containing organic fibres.  
**No asbestos detected. (Submitted sample is too small and a larger sample may produce a different result).**

Reported by,



**Mahen De Silva. BSc, MSc, Grad Dip (Occ Hyg)**  
**Occupational Hygienist / Approved Identifier.**  
**Approved Signatory**



**Accredited for compliance with ISO/IEC 17025 -Testing.**

*The results contained in this report relate only to the sample/s submitted for testing. Australian Safer Environment & Technology accepts no responsibility for whether or not the submitted sample/s is/are representative. Results indicating*

SUITE 710 / 90 GEORGE STREET, HORNSBY NSW 2077 – P.O. BOX 1644 HORNSBY WESTFIELD NSW 1635  
PHONE: (02) 99872183 FAX: (02)99872151 EMAIL: info@ausset.com.au WEBSITE: [www.Ausset.com.au](http://www.Ausset.com.au)





*“No asbestos detected” indicates a reporting limit specified in AS4964 -2004 which is 0.1g/ Kg (0.01%). Any amounts detected at assumed lower level than that would be reported, however those assumed lower levels may be treated as “No asbestos detected” as specified and recommended by AS4964-2004. Trace / respirable level asbestos will be reported only when detected.*

*If the submitted sample is too small there is a possibility that asbestos may not be present in the selected area of the sampled material. Australian Safer Environment & Technology Pty Ltd is not liable if the submitted portion of the sample is free of asbestos and the remaining material has asbestos. This indicates the importance of obtaining and submission of a representative amount /portion of the sample.*

**Mortuary**

Photo No. 001: South-western entrance



The Moulded Fibre Cement door jamb to the at south-western entrance was tested and **proved to be an asbestos-containing material**

Photo No. 002: Original building



The FFCS eave soffit lining to the original building was previously tested by others and **proved to be an asbestos-containing material**

Photo No. 003: Mortuary Storage Room



The FFCS ceiling lining to the Mortuary storage room was referred to a sample previously tested by others that **proved to be an asbestos-containing material**

**Mortuary**

Photo No. 007: Front Extension



The FFCS eave soffit lining to the front extension was tested and **proved NOT to be an asbestos containing material**

Photo No. 008: South-Western Entrance



The FFCS wall cladding to the partition adjacent to the south-western entrance was tested and **proved NOT to be an asbestos containing material**

Photo No. 009: Mortuary



The lagging debris in the ceiling cavity of the mortuary has been remediated and as such has **proved NOT to be an asbestos containing material**

|                         |  |
|-------------------------|--|
| Client Company Name:    | ENV Solutions  |
| Client Company Address: | 313 River Street Ballina NSW 2478                          |
| Contact Name:           | Jake Rozyn   |
| Contact Number:         | 0435 857 751   |
| Contact Email:          | jake@envsolutions.com.au<br>labresults@envsolutions.com.au |

|   |  |   |                                |
|---|--|---|--------------------------------|
| Client Project / Site Ref (Lab Report Title): | 216435 - Taree Manning Hospital - Building 5 | COC Emailed to OCTIEF (Y/N):                  |                                |
| Purchase Order #:                             |  | Email Results To*:                            | jake@envsolutions.com.au       |
| Turn Around Time                              | STANDARD / URGENT                            | Email Invoice To*:                            | labresults@envsolutions.com.au |
|   |  |   | accounts@envsolutions.com.au   |
|   |  | *SENT TO CONTACT EMAIL LISTED IF NOT PROVIDED |                                |

Parameters to be Tested  
 please indicate the test types required along the top and tick which samples require which particular test - include relevant code from the LAB CODES tab where possible

| Lab Ref | Client Sample ID / Information | Date Sampled | Sampled By | Pb in dust | Pb in paint | Comments  |
|---------|--------------------------------|--------------|------------|------------|-------------|---|
| 1       | DS10-1                         | 10/02/2022   | JR         | X          |             | Mortuary north ceiling cavity                           |
| 2       | DS10-2                         | 10/02/2022   | JR         | X          |             | Mortuary ceiling cavity middle                          |
| 3       | DS10-3                         | 10/02/2022   | JR         | X          |             | Mortuary ceiling cavity south                           |
| 4       | Pb10-1                         | 10/02/2022   | JR         | X          |             | Mortuary south window light brown white undercoat paint |
| 5       | Pb10-2                         | 10/02/2022   | JR         | X          |             | Mortuary green paint barge board                        |
| 6       | Pb10-3                         | 10/02/2022   | JR         | X          |             | Mortuary interior white paint walls                     |
| 7       | Pb10-4                         | 10/02/2022   | JR         | X          |             | Mortuary interior blue/grey paint of under coats        |

For Laboratory Use Only

Sample Temperature on Receipt:            °C

Sample Condition on Receipt: A

LIMS Reference #: 02-0722

Date Due:           

Invoice #:           

Where METALS are required, specify if Total or Dissolved Metals are required and indicate metals for testing. Include comments on special handling, storage and disposal if required.

Please Tick Payment Method:  Account  Credit Card\*  Electronic Funds Transfer  Cash

\* Payment by credit card incurs a 2.5% surcharge - OCTIEF will contact client for credit card details

|                |               |                  |  |                |            |              |         |
|----------------|---------------|------------------|--|----------------|------------|--------------|---------|
| Company:       | ENV Solutions | Retinquished By: |  | Company:       | OCTIEF     | Received By: |         |
| Name:          | Jake Rozyn    |                  |  | Name:          | Jacobhan M |              |         |
| Date and Time: |               |                  |  | Date and Time: | 18/02/22   |              | 12:00pm |
| Signature:     |               |                  |  | Signature:     |            |              |         |

UNCONTROLLED WHEN PRINTED



## CERTIFICATE OF ANALYSIS

Report No. 22-0722

Rev No. 01

|                     |   |                          |            |
|---------------------|---|--------------------------|------------|
| Client:             | Environmental Solutions                         | Date Samples Received:   | 18/02/2022 |
| Client Contact:     |   | Date Analysis Commenced: | 18/02/2022 |
| Client Address:     | 313 River Street<br>Ballina 2478                | No. Samples Received:    | 7          |
|                     |   | No. Samples Analysed:    | 7          |
| Purchase Order #:   |   | Date Issued:             | 23/02/22   |
| Project / Site Ref: | 216435 - Taree Manning Hospital -<br>Building 5 |                          |            |

| Laboratory ID | Sample Description | Sample Date | Total Lead on Swab* | Lead    |
|---------------|--------------------|-------------|---------------------|---------|
| Method        |                    |             | LAB-307             | LAB-307 |
| Units         |                    |             | mg                  | %       |
| LOR           |                    |             | 0.01                | 0.001   |
| 22-0722/1     | DS10-1             | 10/02/2022  | 1.94                |         |
| 22-0722/2     | DS10-2             | 10/02/2022  | 0.13                |         |
| 22-0722/3     | DS10-3             | 10/02/2022  | 0.03                |         |
| 22-0722/4     | Pb10-1             | 10/02/2022  |                     | 2.829   |
| 22-0722/5     | Pb10-2             | 10/02/2022  |                     | 2.522   |
| 22-0722/6     | Pb10-3             | 10/02/2022  |                     | 6.381   |
| 22-0722/7     | Pb10-4             | 10/02/2022  |                     | 6.005   |

### General Comments

#### Notes:



- I. OCTIEF accepts no responsibility for the collection, packaging and transportation of samples submitted by external parties
- II. All samples are analysed as received and the results contained within this report relate only to the sample(s) submitted for analysis.
- III. Measurement uncertainty data is available [here](#).
- IV. NATA Accreditation Number: 15172
- V. Accredited for compliance with ISO/IEC 17025 – Testing
- VI. This document may not be reproduced except in full
- VII. Tests not covered by NATA are denoted with \*

### Approved Signatories



Checked By: Lachlan Modina  
Senior Laboratory Technician



Approved By: Daryl Surkitt  
Manager Laboratory Technical Services



**AUSTRALIAN SAFER ENVIRONMENT & TECHNOLOGY PTY LTD**

Suite 710/90 George Street Hornsby NSW 2077 PO Box 1644 Hornsby Westfield NSW 1635

Ph: 02 9987 2183 Fax: 02 9987 2151 Email: [aset@bigpond.net.au](mailto:aset@bigpond.net.au)

| ASET JOB NO: AS6T99141/102321/1-23                                      |           |       |      |           | Contact Name: Jake Rozyn   |   | Asbestos in Material | Asbestos in Soil | Asbestos in Dust | Asbestos Fibre Count | Asbestos in Water | Asbestos WA/NEPM |
|---|-----------|-------|------|-----------|--|---|----------------------|------------------|------------------|----------------------|-------------------|------------------|
| Company Name & Address: ENV Solutions<br>PO Box 248<br>Ballina NSW 2478 |           |       |      |           | Job No: 216435   |   |                      |                  |                  |                      |                   |                  |
| Contact Ph: 0435 857 751  |           |       |      |           | Project Name: Taree Manning Hospital – B2  |   |                      |                  |                  |                      |                   |                  |
|   |           |       |      |           | Email Results to: <a href="mailto:jake@envsolutions.com.au">jake@envsolutions.com.au</a> ;<br><a href="mailto:labresults@envsolutions.com.au">labresults@envsolutions.com.au</a> |   |                      |                  |                  |                      |                   |                  |
|   | Sample ID | Date  | Type | Container | Sample Location  |   |                      |                  |                  |                      |                   |                  |
| 1   | AS08-1    | 08/02 | Bulk | Bag       | B2 L1 NE balcony drain membrane to downpipe  | X |                      |                  |                  |                      |                   |                  |
| 2   | AS08-2    | 08/02 | Bulk | Bag       | B2 L1 NE balcony 2 <sup>nd</sup> waterproof membrane   | X |                      |                  |                  |                      |                   |                  |
| 3   | AS08-3    | 08/02 | Bulk | Bag       | B2 L1 NE balcony encapsulated black bituminous membrane  | X |                      |                  |                  |                      |                   |                  |
| 4   | AS08-4    | 08/02 | Bulk | Bag       | B2 L1 NE balcony window putty  | X |                      |                  |                  |                      |                   |                  |
| 5   | AS08-5    | 08/02 | Bulk | Bag       | B2 L0 vinyl floor tile under carpet under stairs   | X |                      |                  |                  |                      |                   |                  |
| 6   | AS08-6    | 08/02 | Bulk | Bag       | B2 L0 Plant RM25 hot water gasket  | X |                      |                  |                  |                      |                   |                  |
| 7   | AS08-6.1  | 08/02 | Bulk | Bag       | B2 L0 053 north wall infill panel  | X |                      |                  |                  |                      |                   |                  |
| 8   | AS08-7    | 08/02 | Bulk | Bag       | B2 L1 balcony black bituminous waterproofing membrane  | X |                      |                  |                  |                      |                   |                  |
| 9   | AS08-8    | 08/02 | Bulk | Bag       | B2 L2 ceiling cavity north   | X |                      |                  |                  |                      |                   |                  |
| 10  | AS08-9    | 08/02 | Bulk | Bag       | B2 L2 ceiling cavity mid north   | X |                      |                  |                  |                      |                   |                  |
| 11  | AS08-10   | 08/02 | Bulk | Bag       | B2 L2 ceiling hot water gasket   | X |                      |                  |                  |                      |                   |                  |
| 12  | AS08-11   | 08/02 | Bulk | Bag       | B2 L2 ceiling cavity west corner above toilets dust  |   |                      | X                |                  |                      |                   |                  |
| 13  | AS08-12   | 08/02 | Bulk | Bag       | B2 L2 east balcony west wing water proofing  | X |                      |                  |                  |                      |                   |                  |
| 14  | AS08-13   | 08/02 | Bulk | Bag       | B2 L2 east balcony west wing joint mastic  | X |                      |                  |                  |                      |                   |                  |
| 15  | AS08-14   | 08/02 | Bulk | Bag       | B2 L2 vinyl floor tile under carpet near east balcony exit   | X |                      |                  |                  |                      |                   |                  |
| 16  | AS08-15   | 08/02 | Bulk | Bag       | B2 L0 ceiling cavity   | X |                      |                  |                  |                      |                   |                  |
| 17  | AS09-2    | 09/02 | Bulk | Bag       | B2 L2 west balcony joint mastic  | X |                      |                  |                  |                      |                   |                  |
| 18  | AS09-3.0  | 09/02 | Bulk | Bag       | B2 L1 ceiling cavity [about (N) 1039/40/42]  | X |                      |                  |                  |                      |                   |                  |
| 19  | AS09-3.1  | 09/02 | Bulk | Bag       | B2 L1 ceiling cavity   | X |                      |                  |                  |                      |                   |                  |
| 20  | AS09-4    | 09/02 | Bulk | Bag       | B2 L1 ceiling cavity roof water proof  | X |                      |                  |                  |                      |                   |                  |
| 21  | AS09-5    | 09/02 | Bulk | Bag       | B2 subfloor ceiling compressed sheet (bathroom floor   | X |                      |                  |                  |                      |                   |                  |

**URGENT**



**RECEIVED**  
17 FEB 2022  
BY: *Kithura* 9am



**AUSTRALIAN SAFER ENVIRONMENT & TECHNOLOGY PTY LTD**

Suite 710/ 90 George Street Hornsby NSW 2077 PO Box 1644 Hornsby Westfield NSW 1635

Ph: 02 9987 2183 Fax: 02 9987 2151 Email: [aset@bigpond.net.au](mailto:aset@bigpond.net.au)

|  |          |       |      |     |  |   |                  |   |        |                    |  |  |
|--|----------|-------|------|-----|--|---|------------------|---|--------|--------------------|--|--|
| 22   | AS09-5.1 | 09/02 | Bulk | Bag | B2 L1 bituminous waterproofing membrane above MN0901059 & 1058                                 | X |                  |   |        |                    |  |  |
| 23   | AS09-6   | 09/02 | Bulk | Bag | B2 subfloor compressed sheet flooring 33m from end   | X |                  |   |        |                    |  |  |
| Relinquished By: J.Rozyn   |          |       |      |     | Received By: <i>Kithman</i>  |   | Turn around time |   |        | Method of Shipment |  |  |
| Date & Time:   |          |       |      |     | Date & Time: <i>12/2/22 9am</i>  |   | 24 Hrs           | X | 3 Days |                    |  |  |
| Signature:  |          |       |      |     | Signature:  |   | 48 Hrs           |   | 5 Days |                    |  |  |

**RECEIVED**  
 17 FEB 2022  
 BY: *Kithman 9am*

**URGENT**



Our ref : ASET99141 / 102321 / 1 – 23  
Your ref : 216435 – Taree Manning Hospital – B2  
**NATA Accreditation No: 14484**

18 February 2022

ENV Solutions  
PO Box 248  
Ballina NSW 2478



**Attn: Mr Jake Rozyn**

**Accredited for compliance with ISO/IEC 17025 - Testing.**

Dear Jake

### **Asbestos Identification**

This report presents the results of twenty three samples, forwarded by ENV Solutions on 17 February 2022, for analysis for asbestos.

**1.Introduction:** Twenty three samples forwarded were examined and analysed for the presence of asbestos on 17 February 2022.

**2. Methods:** The samples were examined under a Stereo Microscope and selected fibres were analysed by Polarized Light Microscopy in conjunction with Dispersion Staining method (Australian Standard AS 4964 - 2004 and Safer Environment Method 1 as the supplementary work instruction) (Qualitative Analysis only).

**3. Results :** **Sample No. 1. ASET99141 / 102321 / 1. 216435 - AS08-1 - B2 L1 NE balcony drain membrane to downpipe.**  
Approx dimensions 3.1 cm x 2.5 cm x 0.3 cm  
The sample consisted of a fragment of a bituminous material.  
**Chrysotile asbestos detected.**

**Sample No. 2. ASET99141 / 102321 / 2. 216435 - AS08-2 - B2 L1 NE balcony 2<sup>nd</sup> waterproof membrane.**  
Approx dimensions 6.0 cm x 1.7 cm x 0.3 cm  
The sample consisted of a fragment of a bituminous membrane material containing synthetic mineral fibres.  
**No asbestos detected.**

**Sample No. 3. ASET99141 / 102321 / 3. 216435 - AS08-3 - B2 L1 NE balcony encapsulated black bituminous membrane.**  
Approx dimensions 3.8 cm x 0.5 cm x 0.3 cm  
The sample consisted of a fragment of a bituminous material containing organic fibres and synthetic mineral fibres.  
**No asbestos detected.**

**Sample No. 4. ASET99141 / 102321 / 4. 216435 - AS08-4 - B2 L1 NE balcony window putty.**  
Approx dimensions 4.0 cm x 1.7 cm x 0.5 cm  
The sample consisted of fragments of soft mastic like material.  
**No asbestos detected.**





**Sample No. 5. ASET99141 / 102321 / 5. 216435 - AS08-5 - B2 L0 vinyl floor tile under carpet under stairs.**

Approx dimensions 3.5 cm x 2.5 cm x 0.3 cm

The sample consisted of fragments of floor tile material containing organic fibres.

**No asbestos detected.**

**Sample No. 6. ASET99141 / 102321 / 6. 216435 - AS08-6 - B2 L0 Plant RM25 hot water gasket.**

Approx dimensions 1.4 cm x 1.0 cm x 0.3 cm

The sample consisted of fragments of mastic like material containing organic fibres.

**No asbestos detected.**

**Sample No. 7. ASET99141 / 102321 / 7. 216435 - AS08-6.1 - B2 L0 053 north wall infill panel.**

Approx dimensions 1.6 cm x 1.0 cm x 0.4 cm

The sample consisted of a fragment of a fibro plaster cement material containing organic fibres.

**No asbestos detected.**

**Sample No. 8. ASET99141 / 102321 / 8. 216435 - AS08-7 - B2 L1 balcony black bituminous waterproofing membrane.**

Approx dimensions 1.5 cm x 0.6 cm x 0.2 cm

The sample consisted of a fragment of a bituminous material containing organic fibres.

**Chrysotile asbestos detected.**

**Sample No. 9. ASET99141 / 102321 / 9. 216435 - AS08-8 - B2 L2 ceiling cavity north.**

Approx dimensions 5.0 cm x 5.0 cm x 0.3 cm

The sample consisted of a mixture of dust particles, fragments of fibro plaster containing organic fibres, plaster like material, brick like material and plant matter.

**No asbestos detected.**

**Sample No. 10. ASET99141 / 102321 / 10. 216435 - AS08-9 - B2 L2 ceiling cavity mid north.**

Approx dimensions 5.0 cm x 5.0 cm x 0.2 cm

The sample consisted of a mixture of dust particles, organic fibres, fragments of brick like material, plaster like material and plant matter.

**No asbestos detected.**

**Sample No. 11. ASET99141 / 102321 / 11. 216435 - AS08-10 - B2 L2 ceiling hot water gasket.**

Approx dimensions 1.7 cm x 0.8 cm x 0.2 cm

The sample consisted of fragments of mastic like material containing organic fibres.

**No asbestos detected.**

**Sample No. 12. ASET99141 / 102321 / 12. 216435 - AS08-11 - B2 L2 ceiling cavity west corner above toilets dust.**

Approx dimensions 5.0 cm x 5.0 cm x 0.3 cm

The sample consisted of a mixture of dust particles, organic fibres, plaster like material, wood chips, brick like material and plant matter.

**No asbestos detected.**



**Sample No. 13. ASET99141 / 102321 / 13. 216435 - AS08-12 - B2 L2 east balcony west wing water proofing.**

Approx dimensions 5.0 cm x 5.0 cm x 0.2 cm

The sample consisted of a mixture of dust particles, organic fibres, fragments of brick like material, plaster like material and plant matter.

**No asbestos detected.**

**Sample No. 14. ASET99141 / 102321 / 14. 216435 - AS08-13 - B2 L2 east balcony west wing joint mastic.**

Approx dimensions 1.5 cm x 1.0 cm x 0.3 cm

The sample consisted of a fragment of a bituminous mastic like material containing organic fibres.

**Chrysotile asbestos detected.**

**Sample No. 15. ASET99141 / 102321 / 15. 216435 - AS08-14 - B2 L2 vinyl floor tile under carpet near east balcony exit.**

Approx dimensions 6.0 cm x 5.0 cm x 0.3 cm

The sample consisted of a fragment of a floor tile material containing organic fibres.

**No asbestos detected.**

**Sample No. 16. ASET99141 / 102321 / 16. 216435 - AS08-15 - B2 L0 ceiling cavity.**

Approx dimensions 5.0 cm x 5.0 cm x 0.2 cm

The sample consisted of a mixture of dust particles, organic fibres, fragments of fibro plaster cement\* (Approximate dimension = 0.9cm x 0.5cm x 0.2cm), wood chips, plaster like material and plant matter.

**Chrysotile\* asbestos detected.**

**Sample No. 17. ASET99141 / 102321 / 17. 216435 - AS09-2 - B2 L2 west balcony joint mastic.**

Approx dimensions 2.5 cm x 1.5 cm x 0.4 cm

The sample consisted of fragments of bituminous mastic like material containing organic fibres.

**Chrysotile asbestos detected.**

**Sample No. 18. ASET99141 / 102321 / 18. 216435 - AS09-3.0 - B2 L1 ceiling cavity [about (N) 1039/40/42].**

Approx dimensions 1.5 cm x 1.0 cm x 0.2 cm

The sample consisted of a fragment of a fibre cement material.

**Chrysotile asbestos and Amosite asbestos detected.**

**Sample No. 19. ASET99141 / 102321 / 19. 216435 - AS09-3.1 - B2 L1 ceiling cavity.**

Approx dimensions 0.4 cm x 0.3 cm x 0.2 cm

The sample consisted of a fragment of a fibre cement material.

**Chrysotile asbestos detected.**

**Sample No. 20. ASET99141 / 102321 / 20. 216435 - AS09-4 - B2 L1 ceiling cavity roof waterproof.**

Approx dimensions 2.5 cm x 2.5 cm x 0.5 cm

The sample consisted of a fragment of a bituminous material.

**No asbestos detected.**



**Sample No. 21. ASET99141 / 102321 / 21. 216435 - AS09-5 - B2 subfloor ceiling compressed sheet (bathroom floor).**

Approx dimensions 2.5 cm x 1.8 cm x 0.5 cm

The sample consisted of fragments of fibro plaster cement material containing organic fibres.

**No asbestos detected.**

**Sample No. 22. ASET99141 / 102321 / 22. 216435 - AS09-5.1 - B2 L1 bituminous waterproofing membrane above MN0901059 & 1058.**

Approx dimensions 8.0 cm x 5.0 cm x 0.4 cm

The sample consisted of fragments of bituminous material.

**No asbestos detected.**

**Sample No. 23. ASET99141 / 102321 / 23. 216435 - AS09-6 - B2 subfloor compressed sheet flooring 33m from end.**

Approx dimensions 4.7 cm x 2.0 cm x 0.3 cm

The sample consisted of a fragment of a fibro plaster cement material containing organic fibres.

**No asbestos detected.**

Reported by,

A handwritten signature in black ink, appearing to read 'Mahen De Silva', is written over a white rectangular background.

**Mahen De Silva. BSc, MSc, Grad Dip (Occ Hyg)  
Occupational Hygienist / Approved Identifier.  
Approved Signatory**



**Accredited for compliance with ISO/IEC 17025 - Testing.**

*The results contained in this report relate only to the sample/s submitted for testing. Australian Safer Environment & Technology accepts no responsibility for whether or not the submitted sample/s is/are representative. Results indicating "No asbestos detected" indicates a reporting limit specified in AS4964 -2004 which is 0.1g/ Kg (0.01%). Any amounts detected at assumed lower level than that would be reported, however those assumed lower levels may be treated as "No asbestos detected" as specified and recommended by A4964-2004. Trace / respirable level asbestos will be reported only when detected and trace analysis have been performed on each sample as required by AS4964-2004. When loose asbestos fibres/ fibre bundles are detected and reported that means they are larger handpicked fibres/ fibre bundles, and they do not represent respirable fibres. Dust/soil samples are always subjected to trace analysis except where the amounts involved are extremely minute and trace analysis is not possible to be carried out. When trace analysis is not performed on dust samples it will be indicated in the report that trace analysis has not been carried out due to the volume of the sample being extremely minute.*

*Estimation of asbestos weights involves the use of following assumptions;*

*Volume of each kind of Asbestos present in broken edges have been visually estimated and it has been assumed that volumes remain similar throughout the binding matrix and those volumes are only approximate and not exact. Material densities have been assumed to be similar to commonly found similar materials and may not be exact.*

***The approx weights given above can be used only as a guide. They do not represent absolute weights of each kind of asbestos, as it is impossible to extract all loose fibres from soil and other asbestos containing building material samples using this method. However above figures may be used as closest approximations to the exact values in each case. Estimation and/ or reporting of asbestos fibre weights in asbestos containing materials and soil is out of the Scope of the NATA Accreditation. NATA***



*Accreditation only covers the qualitative part of the results reported. This weight disclaimer also covers weight / weight percentages given.*

**^ denotes loose fibres of relevant asbestos types detected in soil/dust.**

**\* denotes asbestos detected in ACM in bonded form.**

**# denotes friable asbestos as soft fibro plaster and/or highly weathered ACM that will easily crumble.**

Client Company Name: ENV Solutions  
 Client Company Address: 313 River Street Ballina NSW 2478  
 Contact Name: Jake Rozyn  
 Contact Number: 0435 857 751  
 Contact Email: jake@envsolutions.com.au; labresults@envsolutions.com.au

Client Project / Site Ref (Lab Report Title): 216435 - Taree Manning Hospital - Building 2  
 Purchase Order #: STANDARD / URGENT  
 Turn Around Time: STANDARD / URGENT  
 Email Results To\*: jake@envsolutions.com.au  
 Email Invoice To\*: labresults@envsolutions.com.au  
 accounts@envsolutions.com.au  
 COC Emailed to OCTIEF (Y/N):  
 \*SENT TO CONTACT EMAIL LISTED IF NOT PROVIDED

Parameters to be Tested  
 please indicate the test types required along the top and tick which samples require which particular test - include relevant code from the LAB CODES tab where possible

| Lab Ref | Client Sample ID / Information | Date Sampled | Sampled By | Pb in paint | Pb in dust | Comments                                   |
|---------|--------------------------------|--------------|------------|-------------|------------|--|
| 1       | DS08-1                         | 8/02/2022    | JR         | X           |            | B2 L2 Ceiling cavity north                 |
| 2       | DS08-2                         | 8/02/2022    | JR         | X           |            | B2 L2 ceiling mid north                    |
| 3       | DS08-3                         | 8/02/2022    | JR         | X           |            | B2 L2 ceiling cavity west corner           |
| 4       | DS08-4                         | 8/02/2022    | JR         | X           |            | B2 L2 ceiling cavity south                 |
| 5       | Pb08-1                         | 8/02/2022    | JR         | X           |            | B2 L1 NE balcony white paint on windows    |
| 6       | Pb08-2                         | 8/02/2022    | JR         | X           |            | Paint on cement render walls outside 058   |
| 7       | Pb08-3                         | 8/02/2022    | JR         | X           |            | B2 L0 MND0900057 paint from door frame     |
| 8       | Pb08-4                         | 8/02/2022    | JR         | X           |            | B2 L2 white paint windows                  |
| 9       | Pb09-1                         | 9/02/2022    | JR         | X           |            | B2 L1 MND0901046 blue paint to timber work |
| 10      | Pb09-2                         | 9/02/2022    | JR         | X           |            | B2 L2 bathroom light green paint to walls  |
| 11      | DS09-1                         | 9/02/2022    | JR         | X           |            | B2 L1 ceiling cavity west                  |
| 12      | DS09-2                         | 9/02/2022    | JR         | X           |            | B2 L1 ceiling cavity middle                |
| 13      | DS09-3                         | 9/02/2022    | JR         | X           |            | B2 L1 ceiling cavity east                  |

Sample Temperature on Receipt: 4 °C  
 Sample Condition on Receipt: A / UA  
 LIMS Reference #: 22-0723  
 Date Due:  
 Invoice #:

Where METALS are required, specify if Total or Dissolved Metals are required and indicate metals for testing.  
 Include comments on special handling, storage and disposal if required

Please Tick Payment Method:  Account  Credit Card\*  Electronic Funds Transfer  Cash  
 \* Payment by credit card incurs a 2.5% surcharge - OCTIEF will contact client for credit card details

Relinquished By: ENV Solutions  
 Company: ENV Solutions  
 Name: Jake Rozyn  
 Date and Time:  
 Signature:  
 Received By: OCTIEF  
 Company: OCTIEF  
 Name: Lechner M.  
 Date and Time: 18/2/22 12:00pm  
 Signature:



UNCONTROLLED WHEN PRINTED

## CERTIFICATE OF ANALYSIS

Report No. 22-0723

Rev No. 00

|                     |   |                          |            |
|---------------------|---|--------------------------|------------|
| Client:             | Environmental Solutions                         | Date Samples Received:   | 18/02/2022 |
| Client Contact:     |   | Date Analysis Commenced: | 18/02/2022 |
| Client Address:     | 313 River Street<br>Ballina 2478                | No. Samples Received:    | 13         |
|                     |   | No. Samples Analysed:    | 13         |
| Purchase Order #:   |   | Date Issued:             | 23/02/22   |
| Project / Site Ref: | 216435 - Taree Manning Hospital -<br>Building 2 |                          |            |

| Laboratory ID | Sample Description | Sample Date | Total Lead on Swab* | Lead    |
|---------------|--------------------|-------------|---------------------|---------|
| Method        |                    |             | LAB-307             | LAB-307 |
| Units         |                    |             | mg                  | %       |
| LOR           |                    |             | 0.01                | 0.001   |
| 22-0723/1     | DS08-1             | 8/02/2022   | 0.45                |         |
| 22-0723/2     | DS08-2             | 8/02/2022   | 0.14                |         |
| 22-0723/3     | DS08-3             | 8/02/2022   | 0.09                |         |
| 22-0723/4     | DS08-4             | 8/02/2022   | 0.17                |         |
| 22-0723/5     | Pb08-1             | 8/02/2022   |                     | 0.253   |
| 22-0723/6     | Pb08-2             | 8/02/2022   |                     | 2.094   |
| 22-0723/7     | Pb08-3             | 8/02/2022   |                     | 1.361   |
| 22-0723/8     | Pb08-4             | 8/02/2022   |                     | 2.048   |
| 22-0723/9     | Pb09-1             | 9/02/2022   |                     | 7.895   |
| 22-0723/10    | Pb09-2             | 9/02/2022   |                     | 0.196   |
| 22-0723/11    | DS09-1             | 9/02/2022   | 0.33                |         |
| 22-0723/12    | DS09-2             | 9/02/2022   | 0.05                |         |
| 22-0723/13    | DS09-3             | 9/02/2022   | 0.16                |         |

### General Comments

#### Notes:



- I. OCTIEF accepts no responsibility for the collection, packaging and transportation of samples submitted by external parties
- II. All samples are analysed as received and the results contained within this report relate only to the sample(s) submitted for analysis.
- III. Measurement uncertainty data is available [here](#).
- IV. NATA Accreditation Number: 15172
- V. Accredited for compliance with ISO/IEC 17025 – Testing
- VI. This document may not be reproduced except in full
- VII. Tests not covered by NATA are denoted with \*

### Approved Signatories



Checked By: Lachlan Modina  
Senior Laboratory Technician



Approved By: Daryl Surkitt  
Manager Laboratory Technical Services

**Building Two - Administration**

Photo No. 001: 1st Floor Balcony (above Staff Centre)



The Bituminous waterproofing membrane to the 1st floor balcony was previously tested by others and **proved to be an asbestos containing material**

Photo No. 002: 1st Floor Ceiling Void



The Bituminous waterproofing membrane to the 1st floor ceiling void (above Room MN0901059 & 1058) was unable to be sampled **but SHALL be regarded as an asbestos-containing material**

Photo No. 003: 1st floor north east balcony



The Bituminous waterproofing membrane to the 1st floor north east balcony was tested and **proved to be an asbestos containing material**

Photo No. 004: 2nd floor eastern balcony



The Bituminous waterproofing membrane to the 2nd floor eastern balcony was concealed but **SHALL be regarded as an asbestos-containing material**

Photo No. 005: Ground Floor, bulkhead outside MN0900059



The FFCS infill panels to the bulkhead outside MN0900059 were tested and **proved to be an asbestos-containing material**

Photo No. 006: Ground Floor, men's bathroom MN0900044



The Flat Fibre Cement Sheet ceiling lining to the Men's bathroom MN0900044 was tested and **proved to be an asbestos containing material**



Photo No. 007: Ground Floor, men's bathroom ceiling void MN0900044 and MN0900046



The FFCS double ceiling lining to the Men's bathroom ceiling void MN0900044 and MN0900046 was referred to sample 00704 and **SHALL be regarded as an asbestos-containing material**

Photo No. 008: Eave soffit outside room MN0900056




The FFCS eave soffit lining outside Room MN0900063 was previously tested by others and **proved to be an asbestos-containing material**

Photo No. 009: Ground Floor MN0900063




The FFCS ceiling lining to MN0900063 was previously tested by others and **proved to be an asbestos containing material**

Photo No. 010: Ground Floor MN0900056



The FFCS insulation panels the two electrical switchboards in MN0900056 were unable to be sampled **but SHALL be regarded as an asbestos-containing material**

Photo No. 011: Ground Floor MN0900056




The FFCS infill panel behind the electrical switchboard in MN0900056 was unable to be sampled **but, SHALL be regarded as an asbestos-containing material**

Photo No. 012: Ground Floor, North Eastern Entrance Alcove




The FFCS infill panel and soffit lining to the north-eastern entrance alcove were previously tested by others and **proved to be an asbestos containing material**

Photo No. 013: Ground Floor Room MN090028



The insulation panel to the electrical switchboard in MN090028 was unable to be sampled **but SHALL be regarded as an asbestos-containing material**

Photo No. 014: Subfloor of Eastern Wing




The thermal “lagging” insulation to pipework in the subfloor of the eastern wing was previously tested by others and **proved to be an asbestos containing material**

Photo No. 015: 1st Floor, upper cupboard to Room MN0901039



The FFCS ceiling lining to the upper cupboard to MN0901039 **SHALL be regarded as an asbestos-containing material**

Photo No. 016: 1st Floor, upper cupboard to Room MN0901040 and MN0901041



The FFCS ceiling lining to the upper cupboards to Room MN0901040 and MN0901041 **SHALL be regarded as an asbestos-containing material**

Photo No. 017: 1st Floor, upper cupboard to MN0901042



The FFCS ceiling lining to the upper cupboard in MN0901042 **SHALL be regarded as an asbestos-containing material**

Photo No. 018: Entry Portico (off Room MN0900037)




The FFCS awning soffit lining to the entry portico was previously tested and **proved NOT to be an asbestos containing material**

Photo No. 019: 1st Floor Eaves



The FFCS eave soffit lining and infill panels to the eastern wing were tested and **proved NOT to be an asbestos containing material**

Photo No. 020: 2nd Floor (West Wing)



The VFTs to the 2nd floor of the West Wing were tested and **proved NOT to be an asbestos containing material**

Photo No. 021: 2nd floor Eastern Balcony




The mastic joint adhesive in the surface of the 2nd floor eastern balcony was referred to sample AB08 and **proved NOT to be an asbestos containing material**

Photo No. 022: Ground Floor Room MN090010



The FFCS wall lining to Room MN090010 was tested and **proved NOT to be an asbestos containing material**

Photo No. 023: Ground Floor Room MN090024



The FFCS wall lining to Room MN090024 was tested and **proved NOT to be an asbestos containing material**

Photo No. 024: Ground Floor Room MN090027



The thermal insulation to pipework in Room MN090027 was remediated and thus **proved NOT to be an asbestos containing material**





Photo No. 025: Ground Floor Storage Rooms off MN090020 and MN090018



The FFCS wall lining to the storage Rooms off MN090020 and MN090018 was tested and **proved NOT to be an asbestos containing material**

**10 Document Control**

|              |  |
|--------------|--|
| Filename:    | ENV216435 – Review of Environmental Factors Report building<br>MN09_20220325 |
| Job No.:     | 216435   |
| Author:      | Robert Kozik   |
| Reviewed By: | Jake Rozyn   |
| Client:      | Mace   |

| Revision No: | Date:    | Issued By  |   |
|--------------|----------|------------|---|
|              |          | Name       | Signed  |
| R01          | 30/03/22 | H. Chapman |    |
| R02          | 13/09/22 | J. Rozyn   |   |
| R03          | 23/01/23 | R. Kozik   |  |
| R04          | 26/06/23 | R. Kozik   |  |

**Scope of Engagement:**

This report has been prepared by ENV Services PTY LTD (ENV) ABN 98 640 278 977 at the request of Mace Group for the purpose of a HAZMAT Assessment and is not to be used for any other purpose or by any other person or corporation.

This report has been prepared from the information provided to us and from other information obtained as a result of enquiries made by us. ENV accepts no responsibility for any loss or damage suffered howsoever arising to any person or corporation who may use or rely on this document for a purpose other than that described above.

No part of this report may be reproduced, stored or transmitted in any form without the prior consent of ENV.

ENV declares that it does not have, nor expects to have, a beneficial interest in the subject project.

To avoid this advice being used inappropriately it is recommended that you consult with ENV before conveying the information to another who may not fully understand the objectives of the report. This report is meant only for the subject site/project and should not be applied to any other.